

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403605751

Date Received:

11/24/2023

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10071

Name of Operator: HIGHPOINT OPERATING CORPORATION

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Luke Kelly

Phone

970-939-6353

Email

lkelly@civiresources.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 696305384

Inspection Date: 11/07/2023

FIR Submit Date: 11/09/2023

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: HIGHPOINT OPERATING CORPORATION

Company Number: 10071

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

### LOCATION - Location ID: 452726

Location Name: Anschutz-Williams Number: 5-61-27 SWSW County: \_\_\_\_\_

Qtrqr: SWS Sec: 27 Twp: 5N Range: 61W Meridian: 6  
W

Latitude: 40.366717 Longitude: -104.203547

### FACILITY - API Number: 05-123-00 Facility ID: 452726

Facility Name: Anschutz-Williams Number: 5-61-27 SWSW

Qtrqr: SWS Sec: 27 Twp: 5N Range: 61W Meridian: 6  
W

Latitude: 40.366717 Longitude: -104.203547

### CORRECTIVE ACTIONS:

1 ☒ CA# 188075

Corrective Action: Install sign to comply with Rule 605.h.

Date: 11/24/2023

Response: CA COMPLETED

Date of Completion: 11/15/2023

Operator Comment: Identified Condensate Vaults have been appropriately addressed by the Operator to ensure that the proper signage is up to date and visible to comply with Rule 605.h.

COGCC Decision: Approved

COGCC  
Representative: Approved

**2** ☒ CA# 188076

Corrective Action: Comply with Rule 606

Date: 11/24/2023

Response: CA COMPLETED

Date of Completion: 11/15/2023

Operator  
Comment: Operator has removed identified locate flags on location to comply with Rule 606.

COGCC Decision: Approved

COGCC  
Representative: Approved

**3** ☒ CA# 188077

Corrective Action: Install Temporary or repair wildlife protection equipment. Prevent any unauthorized discharge (specify condition if it is E&P waste, improper disposal, trash, etc.) Per Rule 902.b.

Date: 11/24/2023

Response: CA COMPLETED

Date of Completion: 11/15/2023

Operator  
Comment: Operator has installed material to close open separators to prevent unauthorized discharge to comply with Rule 902.b.

COGCC Decision: Approved

COGCC  
Representative: Approved

**4** ☒ CA# 188078

Corrective Action: Comply with Rule 606

Date: 11/24/2023

Response: CA COMPLETED

Date of Completion: 11/15/2023

Operator  
Comment: The Operator has addressed and cleared identified tumbleweed debris to comply with Rule 606.

COGCC Decision: Approved

COGCC  
Representative: Approved

**OPERATOR COMMENT AND SUBMITTAL**

Comment: CA follow-up has been completed for this location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ashley Noonan

Signed: \_\_\_\_\_

Title: Sr Regulatory Analyst

Date: 11/24/2023 5:42:20 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
403605751	FIR RESOLUTION SUBMITTED
403605757	Inspection Resolution Report

Total Attach: 2 Files