

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/22/2023

Submitted Date:

11/29/2023

Document Number:

710500139**FIELD INSPECTION FORM**Loc ID 484357 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10797Name of Operator: DESERT EAGLE OPERATING LLCAddress: 17101 PRESTON RD SUITE 105City: DALLAS State: TX Zip: 75248**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Bulf, Cathy		cathybulf@gmail.com	Desert Eagle Operating llc
Costa, Ryan		ryan.costa@state.co.us	
Butler, Brad	972-345-9195	butleroil@yahoo.com	Desert Eagle Operating llc

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
484357	LOCATION	AC			-	Red Rocks 1-14	EI
484674	WELL	DG	08/31/2023		071-09928	Red Rocks 1-14	EI
485121	SPILL OR RELEASE	AC	09/29/2023		-	Drill Cuttings	EI

General Comment:

This is a follow-up Environmental Inspection for Document #710500007 for the Red Rocks 1-14 Location ID 484674, active well location located in Las Animas County, Colorado

Location

Lease Road:			
Type	Access		
comment:	Lease road has been graded.		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Wellhead placard is not properly set		
Corrective Action:	Comply with Rule 605.g.	Date:	12/15/2023

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities							
Facility ID:	<u>484357</u>	Type:	<u>LOCATION</u>	API Number:	<u>-</u>	Status: <u>AC</u>	Insp. Status: <u>EI</u>
Facility ID:	<u>484674</u>	Type:	<u>WELL</u>	API Number:	<u>071-09928</u>	Status: <u>DG</u>	Insp. Status: <u>EI</u>
Facility ID:	<u>485121</u>	Type:	<u>SPILL OR</u>	API Number:	<u>-</u>	Status: <u>AC</u>	Insp. Status: <u>EI</u>

Environmental**Spill/Remediation:**

Comment: Drill Cuttings remain on location. Operator shall assure liner material used to store E&P waste is impermeable
If the cuttings are transported offsite, records will need to be provided to EPS Staff per Rule 905.b(3).

Corrective Action: Manage Drill Cuttings in compliance with Rule 905

Date: 12/15/2023

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

COGCC Comments

Comment	User	Date
All Corrective Actions identified in Construction and Stormwater Management inspection Document # 713600215 apply until resolved.	sanchezcc	11/29/2023
Lined Trench/Pit has been backfilled. There is an open spill associated with this location, Spill ID 485121. Operator shall continue spill remediation in compliance with Rule 912. If remediation is not completed within 90 days from date of discovery Operator shall continue remediation under a Form 27 per Rule 912.b.(6)B	sanchezcc	11/29/2023
Trash and unused equipment has been removed	sanchezcc	11/29/2023
CA for Vehicle rutting has been resolved	sanchezcc	11/29/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500140	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6338460