

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/22/2023

Submitted Date:

12/01/2023

Document Number:

694100216

FIELD INSPECTION FORM

Loc ID 328117 Inspector Name: Robinson, Taylor On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
 Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
 Address: P O BOX 173779
 City: DENVER State: CO Zip: 80217-

Findings:

- 9 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		cogccinspections@oxy.com	
,		ECMCInspections@Oxy.com	All Inspections
,		COGCCinspections@anadarko.com	All Inspections

General Comment:

This is an environmental inspection for Location ID 328117 HSR-Crouch 10-17 wellpad/TB. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

Comment: [Statewide unnecessary equipment, weeds, waste, and trash requirements](#)

Corrective Action: [Comply with Rule 606](#)

Date: [12/15/2023](#)

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type

Comment: [Fencing compromised due to rills forming near base of fencepost on top of earthen berm. Repair/regrade berm and repair/fix fencepost being affected by stormwater induced rill.](#)

Corrective Action: [Install required equipment to comply with Rule 612.e.](#)

Date: [12/15/2023](#)

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment: Wildlife have created holes in berms in multiple locations compromising the integrity of the earthen berms. Consult with CPW on removal of wildlife.					
Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o.					Date: 12/29/2023

Paint

Condition

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: _____				
Corrective Action: _____				Date: _____

Venting:

Yes/No

Comment: _____

Corrective Action:	Date:
Flaring:	
Type	
Comment:	
Corrective Action:	Date:

Location Construction

Location ID: 328117 CDP: _____

Comment:

Corrective Action: Date: _____

Form 2A COAs:

Comment:

Corrective Action: Date: _____

Wildlife BMPs:

Comment:

Corrective Action: Date: _____

Comment:

Corrective Action: Date: 12/15/2023

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment:

Corrective Action: Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694100217	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6341228