

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/21/2023

Submitted Date:

11/27/2023

Document Number:

700901808**FIELD INSPECTION FORM**Loc ID 320057 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 74165Name of Operator: RENEGADE OIL & GAS COMPANY LLCAddress: 6155 S MAIN STREET #225City: AURORA State: CO Zip: 80016**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Ingvie, Ed	(303) 680-4725	ed@renegadeoilandgas.com	All Inspections
Condill, J.B.	(303) 680-4725	jbcrog@aol.com	All Inspections
Espinosa, Bill		billespinosa30@yahoo.com	Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202429	WELL	SI	06/01/2023	OW	001-07834	MAY 32-6	SI

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		40.000424,-104.476097
Comment:	Rule 906: Stained soil under loadout line.				
Corrective Action:	Control and contain spills/releases and clean up per Rule 906. Corrective Action Date 12/29/2023 to remove stained soil. See attached photo # 2 & 6.				Date: 12/29/2023

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	

Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLS	FIBERGLASS AST		,	
Comment:						
Corrective Action:					Date:	
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:						
Corrective Action:					Date:	
<u>Wells Served By Facilities Above</u>						
API Number		AirsID				
001-07834		API Number		AirsID		
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:					Date:	

Inspected FacilitiesFacility ID: 202429 Type: WELL API Number: 001-07834 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: 06/27/2023 Annual Brhd Completed? _____Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONEEnd Surf Csg Pressure: 0Comment: Appeared to be plumbed to surface

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
CECMC Inspection Report Summary On Tuesday, November 21st, 2023 at approximately 14:01PM I, Inspector Chane Finkenbinder, conducted an on-site inspection. Operator: RENEGADE OIL & GAS Location name: MAY_32-6 API # 001-07834 Location ID #: 320057 County: Adams While there, I observed a shut in well. During this inspection the following possible compliance issues were observed: Rule 906: Stained under loadout line.. Control and contain spills/releases and clean up per Rule 906. Corrective Action Date 12/29/2023 to remove stained soil. See attached photo # 2 & 6. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.	finkenbc	11/27/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403607158	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6335335
700901809	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6335328