

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Berms need to be repaired on location		
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 912.d.(1).		Date: 12/18/2023

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: Ancillary equipment	# 1		
Comment:	crypto equipment		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	plumbed to surface		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	crypto equipment		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Gas motor		

Corrective Action:	Date:
--------------------	-------

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	PBV FIBERGLASS		,

Comment:	Date:
Corrective Action:	Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment: shares containment with oil tank	Date:
Corrective Action:	Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,

Comment:	Date:
Corrective Action:	Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				

Comment: needs repair	Date:
Corrective Action:	Date:

Venting:

Yes/No	NO		Date:
Comment:			
Corrective Action:	Date:		

Flaring:

Type		Date:
Comment:		
Corrective Action:	Date:	

Inspected Facilities

Facility ID: 204896 Type: WELL API Number: 005-06981 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 10/03/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On 11/28/23 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- RRR&S 6-5 Company Name- KPK API- 05-005-07112 In Arapaho County Colorado. While there, I observed PR well During this inspection the following possible compliance issues were observed Berms needs to be repaired on location, see pictures. Berms. Rule 912 d. (1).. 12/18/23 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules. This is a summary of inspection report.</p>	medinaj	11/28/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699505160	inspection pictures	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6342261