

# State of Colorado Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403614301

Date Received:  
12/04/2023

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 55030  
Name of Operator: MCCARTNEY ENGINEERING LLC  
Address: 4251 KIPLING ST STE 575  
City: WHEAT RIDGE State: CO Zip: 80033

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Jack McCartney</u>	<u>(303) 830-7208</u>	<u>jack@mccartneyengineering.com</u>

### COGCC INSPECTION SUMMARY:

FIR Document Number: 709100140  
Inspection Date: 10/18/2023 FIR Submit Date: 10/27/2023 FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: MCCARTNEY ENGINEERING LLC Company Number: 55030  
Address: 4251 KIPLING ST STE 575  
City: WHEAT RIDGE State: CO Zip: 80033

### LOCATION - Location ID: 312244

Location Name: RICE-612N54W Number: 33NENW County: \_\_\_\_\_  
Qtrqtr: NENW Sec: 33 Twp: 12N Range: 54W Meridian: 6  
Latitude: 40.977250 Longitude: -103.415420

### FACILITY - API Number: 05-075-00 Facility ID: 312244

Facility Name: RICE-612N54W Number: 33NENW  
Qtrqtr: NENW Sec: 33 Twp: 12N Range: 54W Meridian: 6  
Latitude: 40.977250 Longitude: -103.415420

### CORRECTIVE ACTIONS:

**1** CA# 187253

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a. Date: 11/28/2023

Response: CA COMPLETED Date of Completion: 11/08/2023

Operator Comment: Done. Oily soil to be disposed at authorized disposal site.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**2** CA# 187254

Corrective Action: Comply with Rule 606

Date: 11/13/2023

Response: CA COMPLETED

Date of Completion: 11/13/2023

Operator Comment: Sheet metal in shed put to use as drip pan under engine lubricator.

COGCC Decision:

COGCC  
Representative:

**3** CA# 187255

Corrective Action: Comply with Rule 606

Date: 11/13/2023

Response: CA COMPLETED

Date of Completion: 11/13/2023

Operator Comment: Old drilling cable (metal piping) and tubing removed. 5 gallon bucket contents removed and placed empty bucket in engine house for future use.

COGCC Decision:

COGCC  
Representative:

**4** CA# 187256

Corrective Action: Install sign to comply with Rule 605.a. and Rule 605.d.

Date: 11/28/2023

Response: CA COMPLETED

Date of Completion: 11/13/2023

Operator Comment: Location ID added to well sign.

COGCC Decision:

COGCC  
Representative:

**5** CA# 187257

Corrective Action: Install or repair wildlife protection equipment. Prevent any unauthorized discharge.

Date: 11/06/2023

Response: CA COMPLETED

Date of Completion: 11/27/2023

Operator Comment: Drum and container removed. Drum moved to Rice #3 location and placed in container that is covered with chicken wire.

COGCC Decision:

COGCC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All CA's complied with.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jack McCartney

Signed: \_\_\_\_\_

Title: Manager

Date: 12/4/2023 4:05:16 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

<b><u>Document Number</u></b>	<b><u>Description</u></b>

Total Attach: 0 Files