

State of Colorado
Energy & Carbon Management Commission



Document Number:
403617076

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Date Received:
12/07/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Jones, Tammy</u>		<u>FarmingtonRegulatoryTechs@hilcorp.com</u>
<u>Shorty, Priscilla</u>	<u>505-324-5188</u>	<u>pshorty@hilcorp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 714000032
Inspection Date: 09/28/2023 FIR Submit Date: 10/11/2023 FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY Company Number: 10133
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 326297

Location Name: HUBER-LEWIS-N35N8W Number: 33SWSE County: _____
Qtrqtr: SWSE Sec: 33 Twp: 35N Range: 8W Meridian: N
Latitude: 37.253786 Longitude: -107.748046

FACILITY - API Number: 05-067-00 Facility ID: 326297

Facility Name: HUBER-LEWIS-N35N8W Number: 33SWSE
Qtrqtr: SWSE Sec: 33 Twp: 35N Range: 8W Meridian: N
Latitude: 37.253786 Longitude: -107.748046

CORRECTIVE ACTIONS:

1 CA# 183730

Corrective Action: Remove unused equipment from the location. Date: 10/28/2023

Response: CA COMPLETED Date of Completion: 12/06/2023

Operator Comment: The unused equipment(wellhead fencing)has been reinstalled.

COGCC Decision: _____

COGCC
Representative:

2 CA# 183731

Corrective Action: Comply with Rule 1002.f. Install or repair required BMPs per Rule 1002.f. BMP's shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to rule 1004. Areas will require additional reclamation and stabilization pursuant to 1003 rules.

Date: 09/28/2023

Response: CA COMPLETED

Date of Completion: 12/06/2023

Operator Comment: The erosion on the southern part of location has been back filled and the drainage has been addressed to stop erosion issue's.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: See attached resolved photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tammy Jones

Signed: _____

Title: Ops/Regulatory Tech

Date: 12/7/2023 7:00:51 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403617080	Resolved Photos
-----------	-----------------

Total Attach: 1 Files