

## State of Colorado

## Energy &amp; Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203

Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403308341

Date Received:

06/19/2023

Spill report taken by:

NEIDEL, KRIS

Spill/Release Point ID:

444035

## SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 912.b. for reporting requirements of spills or releases of E&P Waste, produced Fluids, or unauthorized Releases of natural gas. Submit a Site Investigation and Remediation Workplan (Form 27) if Rule 913.c. applies.

## OPERATOR INFORMATION

Name of Operator: SCOUT ENERGY MANAGEMENT LLC	Operator No: 10779	<b>Phone Numbers</b>
Address: 13800 MONTFORT DRIVE SUITE 100		Phone: (970) 620-3456
City: DALLAS	State: TX	Mobile: (970) 501-5157
Zip: 75240	Contact Person: Chris Patterson	Email: chris.patterson@scoutep.com

☒ Transfer of Operatorship: Pursuant to Rule 912.f, this Supplemental Form 19 is being submitted to designate the Buying Operator as the responsible Operator for this Spill and Release.

## INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 400937295

Initial Report Date: 11/16/2015 Date of Discovery: 11/15/2015 Spill Type: Recent Spill

## Spill/Release Point Location:

QTRQTR NESE SEC 31 TWP 2N RNG 102W MERIDIAN 6

Latitude: 40.097600 Longitude: -108.879000

Municipality (if within municipal boundaries): County: RIO BLANCO

Enter Lat./long measurement of the actual Spill/Release Point. Lat./Long. Data shall meet standards of Rule 216.

## Reference Location:

Facility Type:

☐ Facility/Location ID No

Spill/Release Point Name:

☒ Well API No. (Only if the reference facility is well) 05-103-06263☐ No Existing Facility or Location ID No.

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0

Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0

Estimated Produced Water Spill Volume(bbl): &gt;=100

Estimated Other E&amp;P Waste Spill Volume(bbl): 0

Estimated Drilling Fluid Spill Volume(bbl): 0

Specify:

Has the subject Spill/Release been controlled at the time of reporting?

## Land Use:

Current Land Use: NON-CROP LAND

Other(Specify):

Weather Condition: 45 Sunny

Surface Owner: OTHER (SPECIFY)

Other(Specify): Atlas

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

Sunday (11-15-2015) at approximately 10:00AM a leak occurred on Union Pacific 34-31 injection line. Approximately 168.6 BBLs of produced water and 0BBLs oil were released due to internal corrosion on a 3" coated spool. The lines were shut in immediately upon detection. Vacuum truck recovered estimated 70 BBLs produced water. Spill started at 40.0976, -108.8790 and ended at 40.1022, -108.87. This area will be water washed and soil samples will be taken to meet COGCC 910-1 table.

**List of Agencies and Other Parties Notified Pursuant to Rule 912.b.(7)-(11):**

**OTHER NOTIFICATIONS**

<u>Date</u>	<u>Agency/Party</u>	<u>Contact</u>	<u>Phone</u>	<u>Response</u>
11/15/2015	COGCC	Kris Neidel	970-675-3705	Emailed
11/15/2015	Rio Blanco	Mark Sprague	970-878-9584	Emailed
11/15/2015	Chevron Landman	Chris Cooper	432-687-7730	Emailed

**REPORT CRITERIA**

**Rule 912.b.(1) Report to the Director (select all criteria that apply):**

\_\_\_\_\_ Rule 912.b.(1).A: A Spill or Release of any size that impacts or threatens to impact any Waters of the State, Public Water System, residence or occupied structure, livestock, wildlife, or publicly-maintained road.

Waters of the State: \_\_\_\_\_ Public Water System: \_\_\_\_\_

Residence or Occupied Structure: \_\_\_\_\_ Livestock: \_\_\_\_\_

Wildlife: \_\_\_\_\_ Publicly-Maintained Road: \_\_\_\_\_

\_\_\_\_\_ Rule 912.b.(1).B: A Spill or Release in which 1 barrel or more of E&P Waste or produced fluids is spilled or released outside of berms or other secondary containment.

\_\_\_\_\_ Rule 912.b.(1).C: A Spill or Release of 5 barrels or more of E&P Waste or produced Fluids regardless of whether the Spill or Release is completely contained within berms or other secondary containment.

\_\_\_\_\_ Rule 912.b.(1).D: Within 6 hours of discovery, a Grade 1 Gas Leak. For a Grade 1 Gas Leak from a Flowline, the Operator also must submit the Form 19 – Initial, document number on a Form 44, Flowline Report, for the Grade 1 Gas Leak

Enter the approximate time of discovery \_\_\_\_\_ (HH:MM)

Enter the Document Number of the Grade 1 Gas Leak Report, Form 44 \_\_\_\_\_

Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? \_\_\_\_\_

Enter the Document Number of the Initial Accident Report, Form 22 \_\_\_\_\_

Was there damage during excavation? \_\_\_\_\_

Was CO 811 notified prior to excavation? \_\_\_\_\_

\_\_\_\_\_ Rule 912.b.(1).E: The discovery of 10 cubic yards or more of impacted material resulting from a current or historic Spill or Release. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards.

Estimated Volume of Impacted Solids (cu. yd.): \_\_\_\_\_

\_\_\_\_\_ Rule 912.b.(1).F: The discovery of impacted Waters of the State, including Groundwater. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards. The presence of free product or hydrocarbon sheen on Groundwater or surface water is reportable. The presence of contaminated soil in contact with Groundwater or surface water is reportable. Check all that apply:

- ☐ The presence of free product or hydrocarbon sheen Surface Water
- ☐ The presence of free product or hydrocarbon sheen on Groundwater
- ☐ The presence of contaminated soil in contact with Groundwater
- ☐ The presence of contaminated soil in contact with Surface water

Rule 912.b.(1).G: A suspected or actual Spill or Release of any volume where the volume cannot be immediately determined, including a spill or release of any volume that daylights from the subsurface.

Rule 912.b.(1).H: Spill or Release resulting in vaporized hydrocarbon mists that leave the Oil and Gas Location or Off-Location Flowline right of way from an Oil and Gas Location and impacts or threatens to impact off-location property.

☐ Areas offsite of Oil & Gas Location ☐ Off-Location Flowline right of way

Rule 912.b.(1).I: A Release of natural gas that results in an accumulation of soil gas or gas seeps.

Rule 912.b.(1).J: A Release that results in natural gas in Groundwater.

## REQUEST FOR CLOSURE

**Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.**

Basis for Closure: ☐ Corrective Actions Completed (documentation attached, check all that apply)

☐ Horizontal and Vertical extents of impacts have been delineated.

☐ Documentation of compliance with Table 915-1 is attached.

☐ All E&P Waste has been properly treated or disposed.

☐ Work proceeding under an approved Form 27 (Rule 912.c).

Form 27 Remediation Project No: \_\_\_\_\_

☐ SUSPECTED Spill/Release did not occur or was below Rule 912.a.(5) reporting thresholds.

### OPERATOR COMMENTS:

Scout Energy Management LLC purchased this asset from Chevron USA Inc. and assumes all future liability for Initial Spill Release Report Doc: #400937295.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Chris Patterson

Title: Senior HSE Coordinator Date: 06/19/2023 Email: chris.patterson@scoutep.com

### COA Type

### Description

	A Remediation Project should be started for this spill as it has been greater than 90 days since spill date.
1 COA	

## Attachment List

### Att Doc Num

### Name

403308341	SPILL/RELEASE REPORT(SUPPLEMENTAL)
403625766	FORM 19 SUBMITTED

Total Attach: 2 Files

## General Comments

### User Group

### Comment

### Comment Date

Environmental	ECMC acknowledges the change of operator and responsibility of this spill.	12/14/2023
Environmental	This form was not assigned properly in our database leading to delay in processing the form by EPS staff.	12/14/2023

Total: 2 comment(s)