

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403628337

Date Received:

12/18/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10797

Name of Operator: DESERT EAGLE OPERATING LLC

Address: 17101 PRESTON RD SUITE 105

City: DALLAS State: TX Zip: 75248

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Bulf, Cathy

cathybulf@gmail.com

Sanchez, Chris

chris.sanchez@state.co.us

Butler, Brad

972-345-9195

butleroil@yahoo.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 710500141

Inspection Date: 11/22/2023

FIR Submit Date: 11/29/2023

FIR Status: _____

Inspected Operator Information:

Company Name: DESERT EAGLE OPERATING LLC

Company Number: 10797

Address: 17101 PRESTON RD SUITE 105

City: DALLAS State: TX Zip: 75248

LOCATION - Location ID: 484358

Location Name: Red Rocks

Number: 1-16

County: _____

Qtrqtr: NENE

Sec: 1

Twp: 30S

Range: 55W

Meridian: 6

Latitude: 37.464488

Longitude: -103.518825

FACILITY - API Number: 05-071-

-00

Facility ID: 484358

Facility Name: Red Rocks

Number: 1-16

Qtrqtr: NENE

Sec: 1

Twp: 30S

Range: 55W

Meridian: 6

Latitude: 37.464488

Longitude: -103.518825

CORRECTIVE ACTIONS:

1 CA# 188650

Corrective Action: Properly Install Sign and comply with Rule 605.g.

Date: 11/21/2023

Response: CA COMPLETED

Date of Completion: 12/01/2023

Operator
Comment:

Sign was installed at the wellhead.

COGCC Decision: _____

COGCC
Representative: _____

2 CA# 188651

Corrective Action: Operator shall report the release of E&P Waste within 24 hours per Rule 912. For Drill cuttings

Date: 12/01/2023

Response: CA COMPLETED

Date of Completion: 12/05/2023

Operator Comment: Form 19, Spill Release Report (Initial) Doc. 403614466 was filed on Decmber 5, 2023. The initial submittal date of FIR 170500141 had no contact information and the Operator was not advised until December 4 that a FIR requiring a Form 19 had been submitted.

COGCC Decision: _____

COGCC
Representative: _____

3 CA# 188652

Corrective Action: Maintain Drill Cutting per Rule 905.

Date: 11/21/2023

Response: CA COMPLETED

Date of Completion: 12/06/2023

Operator Comment: To expedite the management of the drill cuttings and prevent any further releases, in compliance with Rule 905.b.(1) and (3), Rule 905.g.(1).c., and Rule 905.e.(1) a., the drill cuttings have been managed as Oily Waste and have been removed from the location and disposed at an approved waste facility. Attached are the manifestos which are also signed by the land fill operator stating they are in acceptance of E&P waste. The land fill operator has been provided copies of the Table 915-1 results for the RR 35-08 well. Interim reclamation commenced December 8th. Notification was provided on Field Operation Notice Form 42, Doc. No. 403620101. In compliance with Rule 1003.c., and the approved Red Rocks 35-08 Interim Reclamation Plan, to decompact soil layers the areas reclaimed were ripped to an estimated depth of eighteen (18) inches except in those areas with restrictive features encountered at a shallower depth.

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: The sign was properly installed - attachment RR 1-16 Wellhead Sign Response.pdf.
To expedite the management of the drill cuttings and prevent any further releases, in compliance with Rule 905.b.(1) and (3), Rule 905.g.(1).c., and Rule 905.e.(1) a., the drill cuttings have been managed as Oily Waste and have been removed from the location and disposed at an approved waste facility. Attached are the manifestos which are also signed by the land fill operator stating acceptance of E&P waste. The land fill operator has been provided copies of the Table 915-1 results for the RR 1-16 well. Interim reclamation commenced December 8th; notification was provided on Field Operation Notice Form 42, Doc. No. 403611699. In compliance with Rule 1003.c., and the approved Red Rocks 1-16 Interim Reclamation Plan, to decompact soil layers the areas reclaimed were ripped to an estimated depth of eighteen (18) inches except in those areas with restrictive features encountered at a shallower depth. An initial Form 19, Spill Release Report, Doc. 403614466, was filed December 5h - attachment RR 1-16 Form 19 403614466.pdf,

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Cathy Bulf

Signed: _____

Title: Manager

Date: 12/18/2023 2:29:07 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403628390	RR 1-16 Drill Cuttings Manifesto and Receipts
403628394	RR 1-16 Drill Cuttings Removed
403628411	RR 1-16 Form 19 Initial
403628446	RR 1-16 Wellhead Sign Initial Placement

Total Attach: 4 Files