

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403194071

Date Received:

10/11/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Victoria Dizghinjili</u>	<u>303-825-4822</u>	<u>vdizghinjili@kpk.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 699503934

Inspection Date: 05/12/2022

FIR Submit Date: 05/12/2022

FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC Company Number: 46290
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 320454

Location Name: BOXELDER-61S65W Number: 28SENW County: ADAMS
Qtrqr: SENW Sec: 28 Twp: 1S Range: 65W Meridian: 6
Latitude: 39.939444 Longitude: -104.673333

FACILITY - API Number: 05-001- -00 Facility ID: 203809

Facility Name: BOXELDER Number: 22-28
Qtrqr: SENW Sec: 28 Twp: 1S Range: 65W Meridian: 6
Latitude: 39.939444 Longitude: -104.673333

CORRECTIVE ACTIONS:

1 ☒ CA# 161843

Corrective Action: Venting/flaring issue may be present on this site. COGCC data shows that KPK produced, and used same amount of gas since 12/1/18, SI. From 7/1/18 to 11/1/18, previous gas production was several times more than what was used from 2018 to present. Flare sundry notices were denied for this site. Well has been shut in since 1/1/22 according to COGCC data. There is no gas measurement equipment on location, and no gas meter run as this well was part of the third creek pipeline shut down.

Date: 05/12/2022

Response: CA COMPLETED

Date of Completion: 10/10/2022

This well sells gas through a consolidated gas line that KPK controls at the Box Elder 28-1. KPK's production crew began fueling some equipment in execution of KPK's Gas Capture Plan (Form 4 #402927837). However,

Operator Comment: the minimal gas production during these operations was fully consumed by the equipment on location.

COGCC Decision: Approved pending re-inspection

COGCC Representative: approved pending re inspection

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Victoria Dizghinjili

Signed: _____

Title: Engineering Tech

Date: 10/11/2022 2:46:01 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

403194071	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files