

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/07/2023

Submitted Date:

12/21/2023

Document Number:

714300004

FIELD INSPECTION FORM

Loc ID 481526 Inspector Name: Brown, Kari On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 10 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Graber, Nikki		nikki.graber@state.co.us	
Peterson, John		jpeter@kpk.com	KPK environmental
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.
, KPK		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
481527	SPILL OR RELEASE	CL	07/14/2022		-	Jilison 2A	EI

General Comment:

[This is an environmental inspection to determine progress on Spill ID 481527/Remediation Project No 23092. Any corrective actions from previous inspections that have not been addressed are still applicable.](#)

[There were no operator or contract environmental personnel on location at the time of this field inspection.](#)

[Photos attached to document site conditions.](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	BMPs within the open excavation have degraded and become trash.		
Corrective Action:	Comply with good housekeeping Rule 606.	Date:	12/28/2023
Type	WEEDS		
Comment:	Weeds completely overgrown throughout the location including within and outside of the excavation and through the excavation fencing.		
Corrective Action:	Comply with Rule 606.	Date:	12/28/2023

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type			
Comment:	Fencing around the excavations are inadequate. Fencing has fallen in some areas of the excavation and weeds have grown through the fencing, tearing the fencing in multiple places.		
Corrective Action:	Operators will fence or cover open trench/excavation to prevent access when sites are not attended Remediation Safety fence Rule 913.b.(5)B.	Date:	12/28/2023

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 481527 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Remediation excavation is open. Water was observed within the excavation. One monitoring well was observed outside the open excavation. Salt crust was visible on excavation sidewalls.

Corrective Action: In accordance with 913.d.(1) Operator will investigate impacts to soil, Groundwater, and surface water as soon as the impacts are discovered. Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)	
	Comment	Stockpile has been removed from location, however the liner under the stockpile is still on location, is torn in various spots, and has weeds growing through the liner.			
	Corrective Action				Date: _____

Spill/Remediation:

Comment: Quarterly reporting is required for Remediation Project #23092. Operator is past due on quarterly reporting. The last approved Supplemental Form 27 was received on July 28, 2022 (Doc # 403096666)

Corrective Action: In accordance with Rule 913.e.(3), Operator will adopt and maintain a quarterly reporting schedule. Operator will maintain quarterly reporting until the site investigation is complete and the implementation schedule can be updated. This location was included in NOAV # 403513701 for violation of Rule 913.e.(3) Date: 10/26/2022

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
714300005	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6368861