



August 25, 1965

Kingwood Oil Company
First National Bank Building
Oklahoma City, Oklahoma 73100

Gentlemen:

On your July 1965 Operator's Monthly Production Report (OGCC-7) for your Xenia-West Unit, Washington County, Colorado, you noted the well that had been producing from the "D" sand was no longer producing, and that you have one more well producing from the "J" sand.

After going through the files, we have assumed that the "D" well referred to is the No. 5 Minkler, NE SE 11-2N-54W, and that you have re-completed it in the "J" sand. If this is the case, it will be necessary for you to submit a Sundry Notice and Report (OGCC-4), showing what work was performed on the well. A Producer's Certificate of Clearance (OGCC-10) will also be required on this well.

If our assumption, as stated above, is not correct, please let us know what well or wells are involved in this change.

Your early attention to this matter will be appreciated.

Very truly yours,

OIL AND GAS CONSERVATION COMMISSION

H. H. Morrell, Associate Petroleum Engineer

HHM:cm

✓

✓