



**Location**

Overall Good:

**Signs/Marker:**

Type	DRILLING/RECOMP		
Comment:	adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type			
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 264868 Type: WELL API Number: 123-21120 Status: SI Insp. Status: SI

**BradenHead**

Date of Last Brhd Test: 12/18/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 27 Fluid Type: NONE  
 End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Workover**

Comment:

Corrective Action:

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary                      On Thursday 12-14-2023 at approximately 1440 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Form 42 MIRU Doc # 403633131, 42 PA Doc 403633144. Operator: Oxy/Kerr McGee                      Location name:                      Location ID # 331682                      Well Name: Burch 3-1A                      API # 05-123-21120                      County: Weld                      Weather: Clear, Sunny.                      Location: Dry.                      While there, I observed a wellsite, with active WO/P&amp;A operations at the time of the inspection.                      During this inspection, I observed no compliance issues:                      See attached photos.                      I spoke with Oxy WS Supervisor Victor Ildelfonso about the current operations, MIRU this morning and are Axis Energy Services Wireline are currently RU and setting a CIBP at 7,700' over the J Sand perms at 7,756' &amp; 7,776'.                      No follow up site inspection is needed to ensure that the addressed Compliance issues comply with ECMC rules.</p>	revasr	12/28/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702402741	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6375699">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6375699</a>