



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Wellhead		
Corrective Action:		Date:	

**Equipment:**

Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	automation		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	appears plumbed/partially exposed to surface		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 262876 Type: WELL API Number: 123-20799 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 07/12/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 100 Fluid Type: GAS

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary                      On Thursday 12-29-2023 at approximately 1325 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection:                      Operator: Civitas/Crestone Peak Resources                      Location name:                      Location ID #331503                      Well Name: Lone 31-10                      API # 05-123-20799                      County: Weld                      Weather: Clear, Sunny.                      Location: Dry.                      While there, I observed a wellsite, SI at the time of the inspection.                      During this inspection, I observed no compliance issues:                      See attached photos.                      No follow up site inspection is needed to ensure that the addressed Compliance issues comply with ECMC rules.</p>	revasr	12/29/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702402747	Location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6376882">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6376882</a>