

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 (303) 894-2100 Fax: (303) 894-2109



FOR OGCC USE ONLY

BRADENHEAD TEST REPORT

Step 1. Record all tubing and casing pressures as found.
Step 2. Sample now, if intermediate or surface casing pressure >25 psi. In sensitive areas, 1 psi.
Step 3. Conduct Bradenhead test.
Step 4. Conduct intermediate casing test.
Step 5. Send report to BLM within 30 days and to OGCC within 10 days. Include wellbore diagram if not previously submitted or if wellbore configuration has changed since prior program. Attach gas and liquid analyses if sampled.

1. OGCC Operator Number: _____
2. Name of Operator: T-Rex
3. BLM Lease No: _____
4. API Number: _____
5. Multiple completion? ☐ Yes ☒ No
6. Well Name: Linnear Number: 2-R
7. Location (QtrQtr, Sec, Twp, Rng, Meridian): _____
8. County: Adams
9. Field Name: _____
10. Minerals: ☒ Fee ☐ State ☐ Federal ☐ Indian

11. Date of Test: 12-28-23
12. Well Status: ☐ Flowing ☒ Shut In
☐ Gas Lift ☐ Pumping ☐ Injection
☐ Clock/Intermittent
☐ Plunger Lift
13. Number of Casing Strings:
☒ Two ☐ Three ☐ Liner?

14. STEP 1: EXISTING PRESSURES
Record all pressures as found
Tubing: _____
Fm: _____
Tubing: 0#
Fm: J-sand
Prod. Casing: 2#
Fm: J-sand
Intermediate Cag: _____
Surface Casing: 0#

15. STEP 2: See instructions above.

16. STEP 3: BRADENHEAD TEST

Buried valve? ☐ Yes ☒ No Confirmed open? ☒ Yes ☐ No

With gauges monitoring production, intermediate casing and tubing pressures, open surface casing (bradenhead) valve (if no intermediate casing, monitor only the production casing and tubing pressures.) Record pressures at five minute intervals. Define characteristics of flow in "Bradenhead Flow" column using letter designations below:
O = No Flow; C = Continuous; D = Down to 0; V = Vapor
H = Water H2O; M = Mud; W = Whimper; S = Surge; G = Gas

BRADENHEAD SAMPLE TAKEN?
☐ Yes ☒ No ☐ Gas ☐ Liquid
Character of Bradenhead fluid: ☐ Clear ☐ Fresh
☐ Sulfur ☐ Salty ☐ Black
☐ Other: (describe) None
Sample cylinder number: _____

Elapsed Time (Min:Sec)	Fm: <u>J-sand</u> Tubing:	Fm: <u>J-sand</u> Tubing:	Production Casing PSIG	Intermediate Casing PSIG	Bradenhead Flow:
00:					
05:					
10:					
15:					
20:					
25:					
30:					
11:30 A					
11:35					
11:40					
11:45					
11:50					
11:55					
12:00 N					

Note instantaneous Bradenhead PSIG at end of test: 0#

17. STEP 4: INTERMEDIATE CASING TEST

Buried valve? ☐ Yes ☐ No Confirmed open? ☐ Yes ☐ No

With gauges monitoring production casing and tubing pressures, open the intermediate casing valve. Record pressures at five minute intervals. Characterize flow in "Intermediate Flow" column using letter designations below:
O = No Flow; C = Continuous; D = Down to 0; V = Vapor
H = Water H2O; M = Mud; W = Whimper; S = Surge; G = Gas

INTERMEDIATE SAMPLE TAKEN?
☐ Yes ☐ No ☐ Gas ☐ Liquid
Character of Intermediate fluid: ☐ Clear ☐ Fresh
☐ Sulfur ☐ Salty ☐ Black
☐ Other: (describe) _____
Sample cylinder number: _____

Elapsed Time (Min:Sec)	Fm: _____ Tubing:	Fm: _____ Tubing:	Production Casing PSIG	Intermediate Casing PSIG	Intermediate Flow
00:					
05:					
10:					
15:					
20:					
25:					
30:					

Note instantaneous Intermediate Casing PSIG at end of test: _____

18. Comments: _____

19. STEP 5: See instructions above.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.
Test Performed by: Vic Behrens Title: Lease Operator Phone: 303-810-6382
Signed: Vic Behrens Title: _____ Date: 12-28-2023
WITNESSED BY: _____ Title: _____ Agency: _____

Note: Csg. Blew down and trickled a little Had rest of test.