


TEP Rocky Mountain LLC
Federal 298 27-5
Location ID: 316109



Access road to location



Tank labeling missing required information

TEP Rocky Mountain LLC
Federal 298 27-5
Location ID: 316109



Separator leaking outside and on the ground



Separator left open

**TEP Rocky Mountain LLC
Federal 298 27-5
Location ID: 316109**



Location from Northwest corner



Location from Southwest corner

TEP Rocky Mountain LLC
Federal 298 27-5
Location ID: 316109



Location from Southeast corner



Location from Northeast corner