

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403630587

Date Received:  
12/19/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10651  
Name of Operator: VERDAD RESOURCES LLC  
Address: 1125 17TH STREET SUITE 550  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

| Contact Name            | Phone               | Email                                |
|-------------------------|---------------------|--------------------------------------|
| <u>Michael Cugnetti</u> | <u>720-845-6901</u> | <u>mcugnetti@verdadresources.com</u> |

COGCC INSPECTION SUMMARY:

FIR Document Number: 708200696  
Inspection Date: 11/08/2023 FIR Submit Date: 11/16/2023 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: VERDAD RESOURCES LLC Company Number: 10651  
Address: 1125 17TH STREET SUITE 550  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 423036

Location Name: Wickstrom Number: 7-11-5-60 County: \_\_\_\_\_  
Qtrqr: Lot 1 Sec: 7 Twp: 5N Range: 60W Meridian: 6  
Latitude: 40.422450 Longitude: -104.144270

FACILITY - API Number: 05-087-00 Facility ID: 423036

Facility Name: Wickstrom Number: 7-11-5-60  
Qtrqr: Lot 1 Sec: 7 Twp: 5N Range: 60W Meridian: 6  
Latitude: 40.422450 Longitude: -104.144270

CORRECTIVE ACTIONS:

1  CA# 188309

Corrective Action: Properly dispose of oily waste in accordance with Rule 905.e. The location will remain out of compliance until the corrective action has been resolved. Date: 11/08/2023

Response: CA COMPLETED Date of Completion: 12/08/2023

Operator Comment: Stained soil removed from at and around wellhead. See attached photo documentation of corrective actions.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

3  CA# 188311

Corrective Action: Comply with Rule 1002.f. The location will remain out of compliance until the corrective action has been resolved.

Date: 11/08/2023

Response: CA COMPLETED

Date of Completion: 12/08/2023

Operator Comment: Production pad areas soil has been stabilized and sediment trap maintenance has occurred and debris and animal burrows have been removed. See attached photo documentation of corrective actions.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Cugnetti

Signed:

Title: Director of EHS&R

Date: 12/19/2023 3:20:01 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u>                         |
|------------------------|--|
| 403630587              | FIR RESOLUTION SUBMITTED                   |
| 403630609              | photo documentation of corrective actions. |

Total Attach: 2 Files