

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403640066

Date Received:
12/29/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

rbucogccinspectionreports@chevron.onmicrosoft.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 708200743

Inspection Date: 12/06/2023

FIR Submit Date: 12/08/2023

FIR Status: _____

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 421834

Location Name: Igo Creek Number: 09-13H County: _____

Qtrqr: SESE Sec: 13 Twp: 9N Range: 59W Meridian: 6

Latitude: 40.745092 Longitude: -103.918614

FACILITY - API Number: 05-123-00 Facility ID: 421834

Facility Name: Igo Creek Number: 09-13H

Qtrqr: SESE Sec: 13 Twp: 9N Range: 59W Meridian: 6

Latitude: 40.745092 Longitude: -103.918614

CORRECTIVE ACTIONS:

1 CA# 189066

Corrective Action: Comply with Rule 606. The location will remain out of compliance until the corrective action has been resolved.

Date: 12/06/2023

Response: CA COMPLETED

Date of Completion: 12/22/2023

Operator Comment: complied with rule 606

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

2 CA# 189067

Corrective Action: Install or repair wildlife protection equipment per Rule 902.b. The location will remain out of compliance until the corrective action has been resolved.

Date: 12/06/2023

Response: CA COMPLETED

Date of Completion: 12/22/2023

Operator Comment: complied with rule 902.b.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

3 CA# 189068

Corrective Action: Properly dispose of oily waste in accordance with Rule 905.e. The location will remain out of compliance until the corrective action has been resolved.

Date: 12/06/2023

Response: CA COMPLETED

Date of Completion: 12/22/2023

Operator Comment: complied with rule 905.e.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment: complied with rule 606, 905,e., and 902.b. please see attached photo

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Isaiah Flores

Signed: _____

Title: HSE

Date: 12/29/2023 10:52:56 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403640066	FIR RESOLUTION SUBMITTED
403640072	pic
403640073	pic
403640074	pic

Total Attach: 4 Files