

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403639977

Date Received:
12/29/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

rbucogccinspectionreports@chevron.onmicrosoft.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 708200741

Inspection Date: 12/06/2023

FIR Submit Date: 12/08/2023

FIR Status: _____

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 430712

Location Name: TIMBRO FEDERAL Number: LD18-74HN County: _____

Qtrqtr: SWSE Sec: 18 Twp: 9N Range: 58W Meridian: 6

Latitude: 40.744478 Longitude: -103.904172

FACILITY - API Number: 05-123-00 Facility ID: 430712

Facility Name: TIMBRO FEDERAL Number: LD18-74HN

Qtrqtr: SWSE Sec: 18 Twp: 9N Range: 58W Meridian: 6

Latitude: 40.744478 Longitude: -103.904172

CORRECTIVE ACTIONS:

1 CA# 189061

Corrective Action: Install or repair wildlife protection equipment per Rule 902.b. The location will remain out of compliance until the corrective action has been resolved.

Date: 12/06/2023

Response: CA COMPLETED

Date of Completion: 12/12/2023

Operator Comment: Complied with Rule 902.b. Please see attached pics

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

2 CA# 189062

Corrective Action: Properly dispose of oily waste in accordance with Rule 905.e. The location will remain out of compliance until the corrective action has been resolved.

Date: 12/06/2023

Response: CA COMPLETED

Date of Completion: 12/12/2023

Operator Comment: Complied with Rule 905.b.Please see attached pics

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

3 CA# 189063

Corrective Action: Install sign to comply with Rule 605.g. The location will remain out of compliance until the corrective action has been resolved.

Date: 12/06/2023

Response: CA COMPLETED

Date of Completion: 12/21/2023

Operator Comment: Complied with Rule 605.g.Please see attached pics

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

4 CA# 189064

Corrective Action: Comply with Rule 1003. The location will remain out of compliance until the corrective action has been resolved.

Date: 12/06/2023

Response: CA COMPLETED

Date of Completion: 12/21/2023

Operator Comment: Complied with Rule 1003.Please see attached pics

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

5 CA# 189065

Corrective Action: Comply with Rule 1002.f. The location will remain out of compliance until the corrective action has been resolved.

Date: 12/06/2023

Response: CA COMPLETED

Date of Completion: 12/21/2023

Operator Comment: Complied with Rule 1002.Please see attached pics

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment: Complied with Rule 1002, 902.b., 1003, 605.g. and 905.b.Please see attached pics

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Isaiah Flores

Signed: _____

Title: HSE

Date: 12/29/2023 10:20:49 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403639977	FIR RESOLUTION SUBMITTED
403639989	pic
403639992	pic
403639993	pic
403639994	pic
403640006	pic

Total Attach: 6 Files