

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403645335

Date Received:

01/04/2024

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

\*

[rbucogccinspectionreports@chevron.onmicrosoft.com](mailto:rbucogccinspectionreports@chevron.onmicrosoft.com)

### COGCC INSPECTION SUMMARY:

FIR Document Number: 708200783

Inspection Date: 12/28/2023

FIR Submit Date: 01/02/2024

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

### LOCATION - Location ID: 435720

Location Name: BULLEIT FEDERAL PC LG Number: 04-62HN County: \_\_\_\_\_

Qtrqtr: SESE Sec: 4 Twp: 8N Range: 59W Meridian: 6

Latitude: 40.685280 Longitude: -103.972920

### FACILITY - API Number: 05-123-00 Facility ID: 435720

Facility Name: BULLEIT FEDERAL PC LG Number: 04-62HN

Qtrqtr: SESE Sec: 4 Twp: 8N Range: 59W Meridian: 6

Latitude: 40.685280 Longitude: -103.972920

### CORRECTIVE ACTIONS:

1 ☒ CA# 189749

Corrective Action: Properly dispose of oily waste in accordance with Rule 905.e. The location will remain out of compliance until the corrective action has been resolved.

Date: 12/28/2023

Response: CA COMPLETED

Date of Completion: 01/04/2024

Operator Comment: Complied with Rule 905.e.

COGCC Decision: Approved pending re-inspection

COGCC Representative:	Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.		
2	<input checked="" type="checkbox"/> CA# 189750		
Corrective Action:	Install sign to comply with Rule 605.g. The location will remain out of compliance until the corrective action has been resolved.		Date: <u>12/28/2023</u>
Response:	CA COMPLETED		Date of Completion: <u>01/04/2024</u>
Operator Comment:	Complied with Rule 605.g.		
COGCC Decision:	Approved pending re-inspection		
COGCC Representative:	Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.		

OPERATOR COMMENT AND SUBMITTAL	
Comment:	Complied with Rules 905.e. and 605.g.
I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.	
Print Name:	Javier Pellacani
Title:	HSE
Signed:	
Date:	1/4/2024 4:27:00 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403645335	FIR RESOLUTION SUBMITTED
403645353	Location Photo
403645361	Location Photo
403645362	Location Photo
403645363	Location Photo

Total Attach: 5 Files