

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403653811

Date Received:
01/12/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 4 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

rbucogccinspectionreports@chevron.onmicrosoft.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 708200785

Inspection Date: 12/28/2023

FIR Submit Date: 01/02/2024

FIR Status: _____

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 457009

Location Name: LG Number: 04-15 County: _____
MULTI

Qtrqtr: SWSE Sec: 4 Twp: 8N Range: 59W Meridian: 6

Latitude: 40.685060 Longitude: -103.977370

FACILITY - API Number: 05-123- -00 Facility ID: 457009

Facility Name: LG Number: 04-15
MULTI

Qtrqtr: SWSE Sec: 4 Twp: 8N Range: 59W Meridian: 6

Latitude: 40.685060 Longitude: -103.977370

CORRECTIVE ACTIONS:

1 CA# 189751

Corrective Action: Comply with Rule 606 and remove unused equipment or return to service. The location will remain out of compliance until the corrective action has been resolved.

Date: 12/28/2023

Response: CA COMPLETED

Date of Completion: 01/08/2024

Operator Comment: Complied with Rule 606.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

2 CA# 189752

Corrective Action: Comply with Rule 606 and remove weedy debris. The location will remain out of compliance until the corrective action has been resolved.

Date: 12/28/2023

Response: CA COMPLETED

Date of Completion: 01/08/2024

Operator Comment: Complied with Rule 606.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment: Complied with Rule 606.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Javier Pellacani

Signed: _____

Title: HSE

Date: 1/12/2024 3:14:15 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403653811	FIR RESOLUTION SUBMITTED
403653829	Location Photo
403653831	Location Photo

Total Attach: 3 Files