

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/12/2024

Submitted Date:

01/17/2024

Document Number:

694100270**FIELD INSPECTION FORM**Loc ID 329913 Inspector Name: Robinson, Taylor On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 2001 16TH STREET SUITE 900City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		nbl_djbu_inspections@nblenergy.com	ALL INSPECTIONS ONLY
/, Chevron		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections
,		NBL_DJBU_Inspections@NBLENERGY.COM	ALL INSPECTIONS

General Comment:

This is an environmental inspection for Location ID 329913 Spomer 32-16H6 TB. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

Comment:

Weeds and loose barbed wire fencing on location.

Statewide unnecessary equipment, weeds, waste, and trash requirements

Corrective Action:

Comply with Rule 606

Date: 01/31/2024

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

No spills present at time of inspection.

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
Comment: Berm near meter house nonfunctional due to stormwater related erosion. Needs to be filled and recontoured. Use for crude, condensate and produced water. Inadequate berms around tank(s)						
Corrective Action: Repair or install berms or other secondary containment devices per Rule 912.d.(1).						Date: 01/31/2024

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Location Construction

Location ID: 329913 CDP: _____

Comment: _____

Corrective Action: _____ Date: _____

Form 2A COAs:**Comment:** _____

Corrective Action: _____ Date: _____

Wildlife BMPs:**Comment:** _____Corrective Action: _____ **Date:** _____**Comment:** Multiple large rills throughout the location resulting in off-location discharge. Runoff needs to be pulled back. Rills need to be filled and recontoured.**Corrective Action:** Install or repair required BMPs per Rule 1002.f.(2)C **Date:** 01/31/2024**On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

--

Summary of Operator Response to Landowner Issues:

--

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

--

Environmental

Spills/Releases:

Type of Spill:Estimated Spill Volume:

Comment:

No spills/releases observed at time of inspection.

Corrective Action:

Date:

Reportable:GPS: LatLong

Proximity to Surface Water:Depth to Ground Water:

Water Well Complaint:

DWR Receipt Num:Owner Name:GPS :

LatLong

Field Parameters:

Sample Location:

Comment:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403659687	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6398853
694100271	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6398846

Date Run: 1/25/2024 Doc [#694100270]

Page 4 of 4