



BRADENHEAD TEST REPORT

Step 1. Before opening any valves, record all tubing and casing pressures as found.
 Step 2. Collect liquid and gas samples as required; consult Bradenhead Testing and Reporting Instructions and Guidance for field specific Orders at <http://cogcc/reg.html#opguidance>
 Step 3. Conduct Bradenhead test.
 Step 4. Submit Form 17 within 10 days of test. Attach a wellbore diagram if not previously submitted or if wellbore configuration has changed since last wellbore diagram was submitted.
 Step 5. Submit sample analytical results via Form 43.

1. OGCC Operator Number: 10633 3. BLM Lease No: _____
 2. Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
 4. API Number; 05-005-07514-00 5. Multiple completion? Yes No
 6. Well Name: Prosper Farms 4-65 Number: 2-1-6 2BH
 7. Location (QtrQtr, Sec, Twp, Rng, Meridian): NWSW,2,4S,65W,6
 8. County ARAPAHOE 9. Field Name: DJ HORIZONTAL NIOBRARA
 10. Minerals: Fee State Federal Indian

11. Date of Test: 01/23/2024
 12. Well Status: Flowing
 Shut In Gas Lift
 Pumping Injection
 Clock/Intermitter
 Plunger Lift
 13. Number of Casing Strings:
 Two Three Liner?

14. EXISTING PRESSURES

Record all pressures as found	Tubing: <u>1740</u> Fm: _____	Tubing: _____ Fm: _____	Prod Csg <u>1590</u> Fm: _____	Intermediate Csg: _____	Surf. Csg <u>34</u>
-------------------------------	----------------------------------	----------------------------	-----------------------------------	-------------------------	---------------------

BRADENHEAD TEST

With gauges monitoring production, intermediate casing and tubing pressures, open surface casing (Bradenhead) valve (if no intermediate casing, monitor only the production casing and tubing pressures.) Record pressures at five minute intervals.
 Describe character of flow in "Bradenhead Flow" column: O = No Flow; C = Continuous; D = Down to 0; S = Surge; W = Whisper
 Describe fluid type in "Bradenhead Fluid" column: H = Water H₂O; M = Mud; G = Gas; V = Vapor; L = Liquid Hydrocarbon; H & M = Water & Mud; H & G = Water & Gas; H & V = Water & Vapor; M & G = Mud & Gas; M & V = Mud & Vapor; G & V = Gas & Vapor; H & L = Water & Liquid Hydrocarbon; M & L = Mud & Liquid Hydrocarbon; G & L = Gas & Liquid Hydrocarbon; V & L = Vapor & Liquid Hydrocarbon; N = None

Buried valve? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Confirmed open? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No BRADENHEAD SAMPLE TAKEN? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Gas <input type="checkbox"/> Liquid Character of Bradenhead fluid: <input type="checkbox"/> Clear <input type="checkbox"/> Fresh <input type="checkbox"/> Sulfur <input type="checkbox"/> Salty <input type="checkbox"/> Black Other:(describe) _____	Elapsed Time (Min:Sec)	Fm: Tubing	Fm: Tubing:	Prod Csg PSIG	Intermedia Csg PSIG	Bradenhead Flow:	Bradenhead Fluid:	
	00:00	1740		1590		DOWN TO 0	GAS	
	05:00	1733		1587		NO FLOW	NONE	
	10:00	1726		1584		NO FLOW	NONE	
	15:00	1722		1586		NO FLOW	NONE	
	20:00	1717		1588		NO FLOW	NONE	
	25:00	1712		1588		NO FLOW	NONE	
	30:00	1707		1588		NO FLOW	NONE	
REQUIRED - Instantaneous Bradenhead Pressure at End of Test: <u>0</u> PSIG								

INTERMEDIATE CASING TEST

With gauges monitoring production, intermediate casing and tubing pressures, open the intermediate casing valve. Record pressures at five minute intervals.

Describe character of flow in "Intermediate Flow" column: O = No Flow; C = Continuous; D = Down to 0; S = Surge; W = Whisper

Describe fluid type in "Intermediate Fluid" column: H = Water H₂O; M = Mud; G = Gas; V = Vapor; L = Liquid Hydrocarbon; H & M = Water & Mud; H & G = Water & Gas; H & V = Water & Vapor; M & G = Mud & Gas; M & V = Mud & Vapor; G & V = Gas & Vapor; H & L = Water & Liquid Hydrocarbon; M & L = Mud & Liquid Hydrocarbon; G & L = Gas & Liquid Hydrocarbon; V & L = Vapor & Liquid Hydrocarbon; N = None.

Buried valve? <input type="checkbox"/> Yes <input type="checkbox"/> No	Elapsed Time (Min:Sec)	Fm: Tubing	Fm: Tubing:	Prod Csg PSIG	Intermediate Csg PSIG	Intermediate Flow:	Intermediate Fluid:
Confirmed open? <input type="checkbox"/> Yes <input type="checkbox"/> No	00:00						
INTERMEDIATE SAMPLE TAKEN? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Gas <input type="checkbox"/> Liquid	05:00						
	10:00						
	15:00						
	20:00						
Character of Intermediate fluid: <input type="checkbox"/> Clear <input type="checkbox"/> Fresh <input type="checkbox"/> Sulfur <input type="checkbox"/> Salty <input type="checkbox"/> Black Other:(describe) _____ _____	25:00						
	30:00						
	REQUIRED - Instantaneous Intermediate Casing Pressure at End of Test: _____ PSIG						

Comments: Post-Production Bradenhead Test
WBD will be submitted on Form 5A.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Test Performed By: Cap McClure Title: Field Technician Phone: (307) 272-8156

Signed: Stephany Olsen Title: Senior Regulatory Analyst Date: 1/25/2024

Witnessed By: _____ Title: _____ Agency: _____