

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/24/2024

Submitted Date:

01/24/2024

Document Number:

713300556**FIELD INSPECTION FORM**Loc ID 332235 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: **Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Silver, Randy	720-827-6688	randy.silver@state.co.us	
, KPK	303-825-4822	cogcc@kpk.com	all inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271275	WELL	PR	05/01/2023	GW	123-22017	SUTTON 41-21	PR

General Comment:

Location

Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good: ☐

Spills:

Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 271275 Type: WELL API Number: 123-22017 Status: PR Insp. Status: PR**Producing Well**Comment: PR Valves appeared to be open at time of inspection

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 04/26/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Wednesday, January 24, 2024, at approximately 10:30, I, Inspector Michael Kester, conducted an on-site inspection. Location: Sutton 41-21 Operator: KPK API#: 123-22017 County: Weld While there, I observed production site with remote located well. During this inspection the following possible compliance issues were observed: Mechanical Issues, Well Head, Comply with Rule 608e, call emergency phone, report, 24 hr corrective action, photo 3 & 4 Stained Soil, Well Head, Comply with Rule 905e, corrective action 24 hr corrective action, photo 3 & 4 Spoke with John Peterson, crew on the way to make repairs Weather conditions: over cast and dry A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules. This is a summary of inspection report.</p> <p>This inspection does not nullify any orders or NOAV from the ECMC This is a continuing education inspection</p>	kesterm	01/24/2024

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713300559	site pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6406279