

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/25/2024

Submitted Date:

01/29/2024

Document Number:

714300031

FIELD INSPECTION FORM

Loc ID 318666 Inspector Name: Brown, Kari On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|----------------|--------------------------|-----------------------------------|
| Watzman, Ross | (303) 825-4822 | rwatzman@kpk.com | all inspections. |
| , KPK | | cogcc@kpk.com | All Inspections |
| Graber, Nikki | | nikki.graber@state.co.us | |
| Peterson, John | | jpeterson@kpk.com | KPK environmental |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------------------|--------|-------------|------------|---------|------------------------------|-------------|
| 485896 | SPILL OR RELEASE | AC | 01/22/2024 | | - | Julian Pluss #1 Tank Battery | EI |

General Comment:

[This is an environmental inspection to determine progress on Spill ID 485896. Any corrective actions from previous inspections that have not been addressed are still applicable.](#)

[There were no operator or contract environmental personnel on location at the time of this field inspection.](#)

[Photos attached to document site conditions.](#)

Inspected Facilities

Facility ID: 485896 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: No remedial excavation has been conducted on site. Stained soil is visible near the separator and extending to the north and east outside of the containment area.

Corrective Action: In accordance with 913.d.(1) Operator will investigate impacts to soil, Groundwater, and surface water as soon as the impacts are discovered. Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 714300032 | Inspection photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6410955 |