

FORM
6
Rev
11/20

State of Colorado
Energy & Carbon Management Commission



DE	ET	OE	ES
----	----	----	----

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403598049

Date Received:
11/16/2023

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 10699 Contact Name: James Krehmeyer
 Name of Operator: OWN RESOURCES OPERATING LLC Phone: (970) 332-3585
 Address: 305 S RIDGE STREET #6279 Fax: _____
 City: BRECKENRIDGE State: CO Zip: 80424 Email: james.krehmeyer@ownresources.com

For "Intent" 24 hour notice required, Name: _____ Tel: _____
 Email: _____
COGCC contact: _____

Type of Well Abandonment Report: Notice of Intent to Abandon Subsequent Report of Abandonment

API Number 05-125-06460-00
 Well Name: DEVLIN Well Number: 1-33
 Location: QtrQtr: SESW Section: 33 Township: 4S Range: 43W Meridian: 6
 County: YUMA Federal, Indian or State Lease Number: _____
 Field Name: BONNY Field Number: 7325

Only Complete the Following Background Information for Intent to Abandon

Latitude: 39.660666 Longitude: -102.188056
 GPS Data: GPS Quality Value: 2.7 Type of GPS Quality Value: PDOP Date of Measurement: 09/18/2009
 Reason for Abandonment: Dry Production Sub-economic Mechanical Problems
 Other _____
 Casing to be pulled: Yes No Estimated Depth: _____
 Fish in Hole: Yes No If yes, explain details below
 Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below
 Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
NIOBRARA	1546	1562	04/11/2023	B PLUG CEMENT TOP	1496

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	9+7/8	7	j-55	23	0	296	75	296	0	VISU
1ST	7+7/8	4+1/2	j-55	10.5	0	1674	150	1674	370	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 1496 with 2 sacks cmt on top. CIBP #2: Depth 1050 with 2 sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)

Set 105 sacks half in. half out surface casing from 350 ft. to 0 ft. Plug Tagged:

Set _____ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Number of Days from Setting Surface Plug to Capping or Sealing the Well: 204
Surface Plug Setting Date: 04/12/2023 Cut and Cap Date: 11/02/2023

*Wireline Contractor: LOg Tech

*Cementing Contractor: Excell Services

Type of Cement and Additives Used: Neat

Flowline/Pipeline has been abandoned per Rule 1105 Yes No

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Pat Dolezal

Title: Regulatory Specialist Date: 11/16/2023 Email: pat.dolezal@ownresources.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Wolfe, Stephen Date: 1/29/2024

CONDITIONS OF APPROVAL, IF ANY:

COA Type

Description

COA Type	Description
0 COA	

Attachment List

<u>Att Doc Num</u>	<u>Name</u>
2466459	WIRELINER JOB SUMMARY
403598049	WELL ABANDONMENT REPORT (SUBSEQUENT)
403598119	CEMENT JOB SUMMARY
403598127	WELLBORE DIAGRAM
403669989	FORM 6 SUBSEQUENT SUBMITTED

Total Attach: 5 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Engineer	Insp - 701006665 17 42(PA) 27(I) - 403537914 42(FPA), 42(FLO) Form 7 - SI 10/23, 11/23 Uploaded CBL to well file	12/23/2023

Total: 1 comment(s)