

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Pump Jack	# 1				
Bradenhead	# 1				
		PHOTO 5: Bradenhead inaccessible or not visible.			
			Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2). THIS IS THE SECOND NOTICE, IMMEDIATE ACTION IS REQUIRED.		

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	100 BBLS	STEEL AST		38.426101,-105.190024

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date: _____

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 210091 Type: WELL API Number: 043-40028 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 03/21/2022 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

BRADENHEAD TEST HAS BEEN SUBMITTED HOWEVER BRHD IS NOT ACCESSABLE AND IT APPEARS THAT THERE IS NO BRHD IN WELLHEAD ASSEMBLY.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695109084	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6411707