

# State of Colorado Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403671266

Date Received:  
01/30/2024

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10651  
Name of Operator: VERDAD RESOURCES LLC  
Address: 1125 17TH STREET SUITE 550  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Michael Cugnetti</u>	<u>720-845-6901</u>	<u>mcugnetti@verdadresources.com</u>

### COGCC INSPECTION SUMMARY:

FIR Document Number: 708200681  
Inspection Date: 11/02/2023 FIR Submit Date: 11/09/2023 FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: VERDAD RESOURCES LLC Company Number: 10651  
Address: 1125 17TH STREET SUITE 550  
City: DENVER State: CO Zip: 80202

### LOCATION - Location ID: 422744

Location Name: Nelson Number: 17-44-9-60 County: \_\_\_\_\_  
Qtrqtr: SESE Sec: 17 Twp: 9N Range: 60W Meridian: 6  
Latitude: 40.743020 Longitude: -104.108130

### FACILITY - API Number: 05-123-00 Facility ID: 422744

Facility Name: Nelson Number: 17-44-9-60  
Qtrqtr: SESE Sec: 17 Twp: 9N Range: 60W Meridian: 6  
Latitude: 40.743020 Longitude: -104.108130

### CORRECTIVE ACTIONS:

**1** CA# 188099

Corrective Action: Anchor equipment ensuring anchors are engineered to ensure the equipment will resist flotation, collapse, lateral movement, or subsidence per Rule 607. The location will remain out of compliance until the corrective action has been resolved.

Date: 11/02/2023

Response: CA COMPLETED Date of Completion: 11/20/2023

Operator Comment: Equipment secured. See attached photo documentation of corrective action.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

2 CA# 188100

Corrective Action: Perform reclamation in accordance to Rule 1003 for the interim areas and pit area. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until the location meets Rule 1003 standards. Operator shall submit a Form 4 Interim Reclamation Complete notice when the location meets Rule 1003 standards. ECMC may conduct inspections prior to receiving said notice to ensure compliance with Rule 1003.

The location will remain out of compliance until the corrective action has been resolved.

Date: 11/02/2023

Response: CA COMPLETED

Date of Completion: 11/20/2023

Operator  
Comment:

a small population of Colorado List B Noxious weed- canada thistle- was removed

COGCC Decision:

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Cugnetti

Signed:

Title: Director of EHS&R

Date: 1/30/2024 1:44:15 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

403671286	Corrective Action Photo Documentation
-----------	---------------------------------------

Total Attach: 1 Files