

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/24/2024

Submitted Date:

01/24/2024

Document Number:

695109069**FIELD INSPECTION FORM**Loc ID 322257 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 44390Name of Operator: JAVERNICK OILAddress: 3040 E MAINCity: CANON CITY State: CO Zip: 81212**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Javernick, James	719-275-3040/719-671-3787	javernick1@gmail.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210076	WELL	PR	07/16/2002	OW	043-40012	ROBB-HIAWATHA 1	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type PUMP JACK

Comment: CATTLE PANEL

Corrective Action:

Date:

**Equipment:**

corrective date

Type: Bradenhead

# 1

Comment: PHOTO 5: Bradenhead inaccessible or not visible( wellhead tree does not appear to include a Bradenhead in it original install).

Corrective Action: Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).

Date: 01/31/2024

Type: Pump Jack

# 1

Comment:

Corrective Action:

Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1		STEEL AST		38.326215,-105.126728

Comment: PHOTO 6: APPEARS THAT GUAGEHATCH LATCH IS BROKEN OR MISSING ON GUAGE HATCH AND THERE IS NO SAFETY VALVE INSTALLED ON TANK.

Corrective Action: Tanks will function as sealed and ventless with gas released only through a vapor control system or properly sized pressure relief valve. per Rule 608.a.(9). 24 HOURS TO INSTALL PRESSURE RELEIF VALVE.

Date: 02/24/2024

**Paint**

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	210076	Type:	WELL	API Number:	043-40012	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:			Annual Brhd Completed?						
Last Brhd Test Results	Initial Surf Csg Pressure:			Fluid Type:					
	End Surf Csg Pressure:								
Comment:	FILE REPORTS								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: <input type="text"/>						Date: <input type="text"/>
Corrective Action: <input type="text"/>						
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403665869	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6405924">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6405924</a>
695109070	FLIRR VIDEO	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6405916">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6405916</a>
695109071	INSP PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6405917">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6405917</a>