


T9N, R58W



SURFACE HOLE LOCATION: NAD 83
 GROUND ELEVATION= 4723.0'
 LATITUDE= 40.713731°
 LONGITUDE= -103.843786°
 LATITUDE= 40°42'49.430"
 LONGITUDE= -103°50'37.631"

KICKOFF POINT: NAD 83
 LATITUDE= 40.707665°
 LONGITUDE= -103.851710°
 LATITUDE= 40°42'27.595"
 LONGITUDE= -103°51'06.154"

LANDING POINT: NAD 83
 LATITUDE= 40.706084°
 LONGITUDE= -103.849430°
 LATITUDE= 40°42'21.904"
 LONGITUDE= -103°50'57.949"

BOTTOM OF PRODUCTION ZONE: NAD 83
 LATITUDE= 40.706280°
 LONGITUDE= -103.822314°
 LATITUDE= 40°42'22.608"
 LONGITUDE= -103°49'20.329"

BOTTOM HOLE LOCATION: NAD 83
 LATITUDE= 40.706283°
 LONGITUDE= -103.821989°
 LATITUDE= 40°42'22.620"
 LONGITUDE= -103°49'19.160"

CERTIFICATE OF SURVEYOR:

THIS IS TO CERTIFY THAT THE ABOVE PLAT WAS PREPARED FROM FIELD NOTES OF ACTUAL SURVEY MADE BY ME OR UNDER MY SUPERVISION AND TO THE SAME TRUE AND CORRECT TO THE BEST OF MY KNOWLEDGE AND BELIEF. THIS CERTIFICATE DOES NOT REPRESENT A LAND SURVEY THAT OR IMPROVEMENT SURVEY PLAT AS DEFINED BY C.S. 38-51-102 AND CANNOT BE RELIED UPON TO DETERMINE OWNERSHIP.


Randall K. French
 RANDALL K. FRENCH
 PROFESSIONAL LAND SURVEYOR
 COLORADO REGISTRATION NUMBER 38512
 1/26/24

NOTICE: ACCORDING TO COLORADO STATE LAW YOU MAY COMMENCE ANY LEGAL ACTION BASED UPON ANY DEFECT IN THIS SURVEY WITHIN THREE YEARS OF THE DATE OF FIRST DISCOVERY OF SUCH DEFECT. IN NO EVENT MAY ANY ACTION BASED UPON ANY DEFECT IN THIS SURVEY BE COMMENCED MORE THAN TEN YEARS FROM THE DATE ON THE CERTIFICATION SHOWN HEREON.

FEDERAL LEASE CROSSINGS

1) LAT: 40.706152°
 LON: -103.840235°
 LAT: 40°42'22.147"
 LON: -103°50'24.845"
 2083' FSL, 0' FEL

- NOTES:**
- ▲ INDICATES SECTION CORNER.
 - INDICATES CALCULATED CORNER.
 - ELEVATION BASED ON NAVD88 (GEOID18).
 - BASIS OF BEARINGS DERIVED FROM COLORADO COORDINATE SYSTEM OF 1983, NORTH ZONE.
 - ALL MEASURED DISTANCES ARE GRID. COMBINED SCALE FACTOR: .99976710 CALCULATED FROM THE NE. CORNER OF SECTION 34, T9N, R58W.
 - OPERATOR: RYAN GROVES / PDOP = 1.1
 - WELL FOOTAGES ARE MEASURED AT RIGHT ANGLES TO THE SECTION LINES.



609 CONSULTING, LLC

LOVELAND OFFICE
 6706 North Franklin Avenue
 Loveland, Colorado 80538
 Phone 970-776-4331

SHERIDAN OFFICE
 1095 Saberton Avenue
 Sheridan, Wyoming 82801
 Phone 307-674-0609

VERDAD RESOURCES

1125 17th Street, Suite 550
 Denver, Colorado 80202

WELL PAD - SPEED GOAT FED 3432-3435		
SPEED GOAT FED 3435-15H WELL LOCATION CERTIFICATE 455' FNL & 961' FEL (NENE) (SURFACE HOLE LOCATION) 2647' FNL & 2090' FWL (SEW) (KICKOFF POINT) 2083' FSL & 2550' FEL (NWSE) (LANDING POINT) LOCATED IN SECTION 34 2063' FSL & 300' FEL (NESE) (BOTTOM OF PRODUCTION ZONE) 2063' FSL & 210' FEL (NESE) (BOTTOM HOLE LOCATION) LOCATED IN SECTION 35 T9N, R58W, 6TH P.M. WELD COUNTY, COLORADO		
DRAFTED BY:	SJM	CHECKED BY: RKF
DATE DRAFTED:	6/13/23	DATE SURVEYED: 5/22/23
REVISED:	1/26/24	FILE NAME: 22-200

K:\VERDAD\2022_200_BRUNGELSON_2294_T9N_R58W_SEC_32\PLAT\SPEEDGOAT\SPEED GOAT FED 3435.dwg, 1/29/2024, 1:40:23 PM, srundberg