

Weld OEM Spill Report Form

Submitted on	26 January 2024, 4:05PM
Receipt number	1660
Related form version	19

Company

Company name	K.P. Kauffman Company, Inc.
Address	1700 Lincoln Street, Suite 4550
City	Denver
State	Colorado
Zip code	80203

Contact Information

Contact person	John Peterson
Contact phone	720-868-9848
Contact email	jpeterson@kpk.com

About the Spill

Date incident occurred	01/26/2024
How long did the spill/ release occur	unknown
Was 9-1-1 called for this incident	No
Longitude	-104.848634
Latitude	40.076797
Fire depatment/district	Fort Lupton Fire
Where did the incident occur?	Oil and gas facility/pipeline

Oil and Gas Incident

Well site name	Facility 8 @ Pehr 12-1
Section	2
Township	1N
Range	67W
Where did the spill occur	Pipeline
Have you submitted a form 19	No

Product Spilled

Product spilled	oil
Number of barrels spilled	2
Emergency precautions taken	N/A
Extremely hazardous substance	No
Acute or chronic health risks	No
Did the spill affect or end near a waterway, irrigation ditch, or a retention pond?	No
What caused the spill/release?	Corrosion

Narrative

Include specific incident information and mitigation actions taken to stop and clean-up the spill/release

KPK is providing the 24-hr notification of a spill from a leak in the consolidated flowline from Facility 8 (Facility 8 @ Pehr 12-1). Xcel Damage Prevention employee (720-445-1588) contacted KPK about the spill on 1.26.24. KPK personnel immediately went to the site, shut in the wellheads, and isolated the flowline. KPK mobilized a vac truck to evacuate the flowline. The Hydro-Vac is removing fluids/stained soil and hauling it to KPK's Fort Lupton yard. The spill is located between the Kerr McGee Pehr Pooling Unit 1 battery and County Road 23. KPK will install a snow fence around the spill. The surface staining was approximately 72 square feet (6'x12').

Upload documentation collected	image000000.jpg
--------------------------------	-----------------

Acknowledgement

I acknowledge that a written follow-up notice must be submitted to Weld County OEM/LEPC as soon as practicable after the release. The follow-up notice must update information included in the initial notice and provide information on actual response actions taken and advice regarding medical attention necessary for citizens exposed.