

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/06/2024

Submitted Date:

02/06/2024

Document Number:

702502365**FIELD INSPECTION FORM**Loc ID 314373 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10779Name of Operator: SCOUT ENERGY MANAGEMENT LLCAddress: 13800 MONTFORT DRIVE SUITE 100City: DALLAS State: TX Zip: 75240**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Regulatory, Rangely		RangelyRegulatory@scoutep.com	
Johnson, Mike		Mike.Johnson@scoutep.com	
Sanford, Anita	(970) 551-8313	Anita.Sanford@scoutep.com	
Patterson, Chris		Chris.Patterson@scoutep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228597	WELL	PR	09/01/2023	OW	103-05505	EMERALD 4	PR

General Comment:**ECMC Inspection Report Summary**

On Tuesday, 02/06/2024, Inspector Kirby Burchett, conducted a routine field inspection at Scout Energy Management LLC on the Emerald 4 well, Location #314373, in Rio Blanco County, Colorado.

This location is within or in close proximity to Parks and Wildlife (CPW) District and High Priority Habitat area with NSO and Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

While there during normal production operations no compliance issues were observed:

No follow up inspection is required.

LocationOverall Good: ☐**Signs/Marker:**

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	As Location Entrance signs are replaced: The Well name; The Commission's Location identification number (ID #); The Operator's telephone number where it may be reached at all times; and the Telephone number(s) for local emergency services (911 where available) will be required.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	970-675-3700 or 911	
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Bradenhead	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Submersible Pump	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank on containment		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities				
Facility ID: 228597	Type: WELL	API Number: 103-05505	Status: PR	Insp. Status: PR
Producing Well				
Comment:	November 2023 Production Report			
Corrective Action:			Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
				Material Handling And Spill Prevention		

Comment: Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702502369	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6420826