

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403680240

Date Received:

02/09/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10330

Name of Operator: INVESTMENT EQUIPMENT LLC

Address: 558 CASTLE PINES PKWY UNIT B-4

City: CASTLE PINES State: CO Zip: 80108

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Bongers, Brent

bbongers@impetroresources.com

Sanchez, Chris

chris.sanchez@state.co.us

Freese, Steve

steve.freese@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 713600686

Inspection Date: 01/31/2024

FIR Submit Date: 02/02/2024

FIR Status: _____

Inspected Operator Information:

Company Name: INVESTMENT EQUIPMENT LLC

Company Number: 10330

Address: 558 CASTLE PINES PKWY UNIT B-4

City: CASTLE PINES State: CO Zip: 80108

LOCATION - Location ID: 321180

Location Name: STATE OF COLORADO-
635S46W

Number: 16NENE

County: BACA

Qtrqr: NENE Sec: 16 Twp: 35S Range: 46W Meridian: 6

Latitude: 37.001500 Longitude: -102.601230

FACILITY - API Number: 05-009-

-00

Facility ID: 276262

Facility Name: STATE OF COLORADO

Number: 3-16

Qtrqr: NENE Sec: 16 Twp: 35S Range: 46W Meridian: 6

Latitude: 37.001500 Longitude: -102.601230

CORRECTIVE ACTIONS:

1 CA# 191657

Corrective Action: Contact ECMC EPS staff per Rule 912.b.
Comply with 1004 Rules.

Date: _____

Response: CA COMPLETED

Date of Completion: 02/09/2024

Per Rule 912.b. Form 19, Document #403680188 has been submitted.
Per the 1004 Rules, the Operator will continue additional Reclamation activities Spring 2024.

COGCC Representative:	
-----------------------	--

Corrective Action:	Install or repair required BMPs per Rule 1002.f.(2)
--------------------	---

Response: CA COMPLETED

Operator Comment:	Per Rule 1002.f.(2) berms have been put up to prevent further erosion where vegetation has not been reestablished. Please see photos attached.
-------------------	--

COGCC
Representative:

Comment:	
----------	--

Print Name: Amber Barnett

Signed:

Title: Compliance Specialist

Date: 2/9/2024 12:46:54 PM

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403680243	Photo Log

Date Run: 2/9/2024 Doc [#403680240]