

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/08/2024

Submitted Date:

02/10/2024

Document Number:

708301662**FIELD INSPECTION FORM**

Loc ID 335634	Inspector Name: Morris, Matthew	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 10 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
<b>Operator Information:</b> OGCC Operator Number: <u>96850</u> Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u> Address: <u>1058 COUNTY ROAD 215</u> City: <u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

<b>Contact Information:</b>			
Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

<b>Inspected Facilities:</b>							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262537	WELL	PR	12/01/2010	GW	045-08036	CHEVRON NG 44-8	PR
280839	WELL	PR	05/01/2006	GW	045-11376	CHEVRON NG 644-8	PR
280840	WELL	PR	05/05/2006	GW	045-11377	CHEVRON NG 544-8	PR
280841	WELL	PR	12/01/2010	GW	045-11378	CHEVRON NG 444-8	PR
280842	WELL	PR	12/01/2010	GW	045-11379	CHEVRON NG 344-8	PR

**General Comment:**

COGCC Inspection Report Summary

On 2/8/2024 at approximately 10:35, Compliance Inspector Matthew Morris conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/8SESE at Location ID #335634 in Garfield County, Colorado.

Normal production operations were observed.

During the inspection, the following compliance issues were observed:

1) Stormwater; refer to Stormwater section

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/(970) 285-9377

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	
In Containment:	No		
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 5	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 5	
Comment:		
Corrective Action:		Date:
Type: Dehydrator	# 1	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 5	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 5	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	250 bbls	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	262537	Type:	WELL	API Number:	045-08036	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	280839	Type:	WELL	API Number:	045-11376	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	280840	Type:	WELL	API Number:	045-11377	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	280841	Type:	WELL	API Number:	045-11378	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	280842	Type:	WELL	API Number:	045-11379	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Fail					Insufficient gravel
		Compaction				
		Gravel				
Compaction	Fail					Lack of stabilization
		Ditches				
Berms						
Other	Fail					Insufficient tracking BMPs

Comment: Location surface lacks stabilization with insufficient vehicle tracking BMPs in place to minimize transportation of sediment.

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 02/25/2024

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708301663	Photo Log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6425275">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6425275</a>