

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/13/2024

Submitted Date:

02/13/2024

Document Number:

699505458**FIELD INSPECTION FORM**Loc ID 320125 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 31257Name of Operator: FRITZLER RESOURCES INCAddress: P O BOX 114City: FORT MORGAN State: CO Zip: 80701**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
Silver, Randy		randy.silver@state.co.us	
,		gfritzler@bresnan.net	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202747	WELL	PR	02/01/2023	OW	001-08152	WAILES 2	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

OTHER

Comment: Wellhead sign does not have emergency number posted.

Corrective Action: Install sign to comply with Rule 605.d.

Date: 03/13/2024

Type

UNUSED EQUIPMENT

Comment: Unused tanks on locaiton need to be removed from location

Corrective Action: Comply with rule 606

Date: 02/28/2024

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type PUMP JACK

Comment: 4' hog fence

Corrective Action:

Date:

**Equipment:**

corrective date

Type: Bradenhead

# 1

Comment: Plumbed to surface

Corrective Action:

Date:

Type: Deadman # &amp; Marked

# 4

Comment:

Corrective Action:

Date:

Type: Prime Mover

# 1

Comment: gas motor

Corrective Action:

Date:

Type: Pump Jack

# 1

Comment:

Corrective Action:

Date:

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 202747 Type: WELL API Number: 001-08152 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 11/17/2023Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONEEnd Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**COGCC Comments**

Comment

User

Date

ECMC Inspection Report Summary  
 On 2/13/24 I, Inspector Justin Medina conducted an on-site inspection at:  
 Well Name- Wailes 2  
 Company Name- Fritzler Resources INC  
 API- 05-001-08152  
 In Adams County Colorado.  
 While there, I observed PR well  
 During this inspection the following possible compliance issues were observed:  
 Unused equipment. Rule 606. 2/28/24  
 Sign emergency number. Rule 605. d. 3/13/24  
 A follow up on this site inspection needs to be conducted to ensure the compliance issues  
 have been corrected to comply with ECMC rules.  
 This is a summary of inspection report.

medinaj

02/13/2024

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
699505459	inspection pictures	<a href="http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6430167">http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6430167</a>