FORM INSP

> Rev X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109





Inspection Date: 02/12/2024
Submitted Date:

Document Number: 708301672

02/14/2024

FIELD INSPECTION FORM

									<u>-</u>			
Loc ID	Loc ID Inspector Name: On-Site Inspection						Status Summary:					
323782 Morris, Matthew 2A Doc Num:						THIS IS A FOLLOW UP INSPECTION						
Operator Information:												
								NO FOLLOW UP INSPE	CTION F	REQUIRED		
Name of Operator: TEP ROCKY MOUNTAIN LLC Findings:												
								7 Number of Comments				
Address: 1058 COUNTY ROAD 215							1 Number of Corrective Actions					
City:	PARACHUTE	State:	CO		Zip: 8163	5						
							P	ANY CORRECTIVE ACT PREVIOUS INSPECTION BEEN ADDRESSED ARI	NS THÀT	T HAVE NOT		
Contact Inf	formation:											
Contact Na	ame	Phor	Phone		Email			Comment				
, TEP					COGCCInspectionReports@t erraep.com							
Inspected I	Facilities:											
Facility ID	Туре	Status	Status Date		Well Class API Num			Facility Name		Insp Status		
210795	WELL	PR	08/02/2001		GW	045-06553		ARCO MV-31-28		PR		
COGCC Ir	General Comment: COGCC Inspection Report Summary On 2/12/2024 at approximately 14:55, Compliance Inspector Matthew Morris conducted a follow-up inspection at TEP ROCKY MOUNTAIN LLC, ARCO-66S96W/28NESW at Location ID #323782 in Garfield County, Colorado.											
Normal pro	oduction operations	were obs	served.									
During the	inspection, the follo	owing cor	npliance issues	wer	e observed:							
1) Debris	on location											
A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.												
This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.												

	<u>Location</u>								
Overall Good:									
Signs/Marker:									
Туре	WELLHEAD								
Comment:									
Corrective Action:					Date	:			
Туре	OTHER	OTHER							
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.								
Corrective Action:					Date				
Emergency Contact I	Number:								
	Comment: 911/(970) 285-9377								
Corrective Action:	:				Date:				
Good Housekeeping	<u>g:</u>								
Туре	DEBRIS								
Comment:	Debris present on west e	nd of pad (Ste	el pi	pe rail and hog panels).					
Corrective Action:	Remove debris to comply	with Rule 60	6.		Date:	02/21/2024			
Overall Good:									
Spills:									
Туре	Area	Volume							
In Containment: No Comment: Multilple Spills and Releases?									
Fencing/:									
Туре	WELLHEAD								
Comment	Hog panels								
Corrective Action					Date:				
Турє	SEPARATOR								
Comment: Hog panels									
Corrective Action: Date:									
Equipment:						corrective date			
Type: Gas Meter Run # 1									
Comment	:								
Corrective Action:					Date:				
Type: Bird Protectors	#	1							
Comment	:								
Corrective Action	Corrective Action: Date:								
Type: Horizontal Hea	ited Separator #	1							
Comment	:								

Inspector Name: Morris, Matthew Corrective Action: Date: Type: Plunger Lift # 1 Comment: Corrective Action: Date: # 1 Type: Bradenhead Comment: Corrective Action: Date: Venting: Yes/No NO Comment: Corrective Action: Date: Flaring: Type Comment: Corrective Action: Date:

moposter re				Inspected	d Facilities				
Facility ID:	210795	Type:	WELL	API Number:	045-06553	Status: _	PR	Insp. Status:	PR
				Produc	ing Well				
1	omment:								
Corrective	e Action:							Date:	

Reclamation - Storm Water - Pit							
Storm Water:							
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment	
Compaction							
		Compaction					
Gravel							
		Gravel					
Berms							
Comment:	Comment: Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.						
Corrective Action:		Date:					
Pits: X NO SURFACE INDICATION OF PIT							

Attached Documents

You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:

Document Num	Description	URL			
403688020	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6430122			
708301673	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6430103			

Date Run: 2/21/2024 Doc [#708301672]