



00054331

COLORADO OIL & GAS CONSERVATION COMMISSION  
FIELD INSPECTION REPORT

<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
<input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION			
API No. 05- 121 - 7074		LEASE NAME: Shambley #1	
LOCATION: NENE 10 2N-54		OPERATOR: JHS Energy	
DATE: 7-15-97		INSPECTOR: Ed Binkley	
Insp. Type: Pr	Insp. Status: Pr	PA: Y N	Pass/Fail: <input checked="" type="checkbox"/> P <input type="checkbox"/> F Viol.: Y <input type="checkbox"/> N NOV: Y <input type="checkbox"/> N

INSPECTION ITEM	COMMENTS	INPUT
<b>Well ID Signs</b> (Rule 210, 604.c(4))	ok	
<b>Pits (Reserve/Production)</b> (Rule 902, 903, 904, 905)	pit clean	
<b>Fences</b> (Rule 603.b.7, 604.C.(3), 1002.A)		
<b>Tank Battery Equipment</b> (Rule 603.b.3, 604)		
<b>Fire Walls/Berms/Dikes</b> (Rule 603.b.12, 604)	needs berm around tank	
<b>General Housekeeping</b> (Rule 603)	Berm is partially worn down -	
<b>Spills (Oil/Water)</b> (Rule 907)		
<b>Bradenhead</b> (Rule 207.b)		
<b>Drilling Well/Workover</b> (Rule 317)		
<b>Surface Rehabilitation</b> (Rule 1002, 1003, 1004, 1103)		
<b>Miscellaneous</b>	* 1/2" water stream discharged from pit requires health dept permit -	

**CORRECTIVE ACTION REQUIRED:** \*

improve tank berm

Date Corrective Action Required By: 8-30-97

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.