



99999999

~~121-07074~~ 121-07074
STATE OF COLORADO
ND GAS CONSERVATION COMMISSION

DEPARTMENT OF NATURAL RESOURCES
SUITE 380 LOGAN TOWER BUILDING
1580 LOGAN STREET

DENVER, COLORADO 80203
(303) 894-2109 FAX
(303) 894-2100

DENNIS R. BICKNELL
Director
JOHN R. STOWELL
Deputy Director
PATRICIA C. BEAVER
Technical Secretary

ROY ROMER
Governor

Allison Drilling Co Inc.

RE: Lease Violation Notice

Lease : Sheibly
Field : _____
County : Washington
Location: NE NE 10-2N-54

Gentlemen:

An inspection was made of the lease(s) shown above. The following marked conditions were observed to exist at the time of the inspection.

- ☐ Oil accumulation on the water in the retaining pit
- ☒ Tank Berm required or in need of repairs
- ☐ Covered skim pit or tank required
- ☐ Tank identification number missing or incorrect
- ☐ Wellhead sign required per rule 210(a), 604(c)
- ☐ Oil spilled at wellhead or tank battery
- ☐ Weeds, debris or waste material observed at site

REMARKS: 1" stream of water being discharged from pit.

The above condition(s) should be corrected immediately. Any surface accumulation of oil in the retaining pits must be cleaned within ten (10) days after receipt of this notice (Rule 328), and a written report or sundry notice submitted to this office within thirty (30) days after the work is accomplished, advising us of the date and manner in which the correction is made. Any person who fails to comply with this request is subject to the penalties as provided for under statute 34-5-121 of the Colorado Oil and Gas Conservation Act.

E.B. Binkley
Petroleum Engineer

Date of Inspection 4-11-92



00054325