

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/29/2024

Submitted Date:

02/29/2024

Document Number:

698705907**FIELD INSPECTION FORM**Loc ID 318401 Inspector Name: Serna, Abe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	
,		randy.silver@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241231	WELL	SI	11/01/2021	OW	123-09019	UPRR 43 PAN AM I 8	SI

General Comment:[Wellsite Inspection](#)

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Pipe on side of location needs to be removed		
Corrective Action:	Comply with rule 606	Date:	03/29/2024
Type	OTHER		
Comment:	Stained soil around well head from leak:		
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e."	Date:	03/29/2024
Type	OTHER		
Comment:	Mechanical issue: Packing appears to be leaking		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.	Date:	03/29/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Ancillary equipment	# 1		corrective date
Comment:	Electrical panel		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electrical motor		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 241231 Type: WELL API Number: 123-09019 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Si
Flowline valve closed

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: 02/23/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
ECMC Inspection Report Summary On Thursday February 29, 2024 at approximately 1:00 pm pm, I, Inspector Abe Serna, conducted an on-site inspection. Location: UPPR 43 PAN AM 1-8 Operator: KPK API#:123-09020 County: WELD While there, I observed a SI Well During this inspection the following possible compliance issues were observed: Unused equipment: Rule 606 CA Date 3-29-24 See photos Mechanical issue: Rule 608 CA Date 3-29-24 See photo Stained soil: Rule 905a Weather conditions: Sunny A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules. This is a summary of inspection report. Any corrective actions from previous inspections that have not been addressed are still applicable	sernaa	02/29/2024

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403704149	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6448971
698705908	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6448968