

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403716738

Date Received:  
03/12/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10679  
Name of Operator: LOGOS OPERATING LLC  
Address: 2010 AFTON PLACE  
City: FARMINGTON State: NM Zip: 87401

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Lacey Granillo</u>	<u>5057870118</u>	<u>lgranillo@logosresourcesllc.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 714000490  
Inspection Date: 02/29/2024 FIR Submit Date: 03/11/2024 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: LOGOS OPERATING LLC Company Number: 10679  
Address: 2010 AFTON PLACE  
City: FARMINGTON State: NM Zip: 87401

LOCATION - Location ID: 333535

Location Name: BONDAD 33-9-N33N9W Number: 18SEnw County: LA PLATA  
Qtrqr: SEnw Sec: 18 Twp: 33N Range: 9W Meridian: N  
Latitude: 37.106880 Longitude: -107.871120

FACILITY - API Number: 05-067-00 Facility ID: 214113

Facility Name: BONDAD 33-9 Number: 14  
Qtrqr: SEnw Sec: 18 Twp: 33N Range: 9W Meridian: N  
Latitude: 37.106880 Longitude: -107.871120

CORRECTIVE ACTIONS:

1  CA# 192919

Corrective Action: Comply with rule 606, remove and properly dispose of debris. Date: 03/18/2024

Response: CA COMPLETED Date of Completion: 03/12/2024

Operator Comment: Weedy kochia debris observed around the Logos well head has been removed.

COGCC Decision: Approved via an AMI

Per photo included in attachment provided by operator the debris has been removed.

COGCC  
Representative:

2  CA# 192920

Corrective Action: Comply with rule 605. Install or repair sign.

Date: 04/10/2024

Response: CA COMPLETED

Date of Completion: 03/12/2024

Operator  
Comment: Well sign was found on location.

COGCC Decision: Approved via an AMI

COGCC  
Representative: 1. Per photo included in attachment provided by operator the sign has been found.

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Weedy kochia debris observed around the Logos well head has been removed.  
Logos sign was found on location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lacey Granillo

Signed: \_\_\_\_\_

Title: Regulatory Specialist

Date: 3/12/2024 3:27:48 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403716738	FIR RESOLUTION SUBMITTED
403716744	714000490- completed
403716746	714000490- completed

Total Attach: 3 Files