

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/12/2024

Submitted Date:

03/12/2024

Document Number:

699505621

FIELD INSPECTION FORMLoc ID 323256 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
244979	WELL	PR	07/01/2023	GW	123-12774	Wingo, C.E. 2	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	contaminated soil near wellhead, and gas motor needs to be removed.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes. Rule 1002..(2).D	Date:	03/17/2024
Type	OTHER		
Comment:	Mechanical issues with wellhead connections, and gas motor		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.	Date:	03/27/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Plumbed to surface		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Gas motor		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 244979 Type: WELL API Number: 123-12774 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 03/16/2023

Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Annual bradenhead test is not current. Contact ECMC engineering

03/22/2024

Corrective Action: Comply with rule 419 5.c.

Date:

COGCC Comments

Comment

User

Date

ECMC Inspection Report Summary
On 3/12/24 I, Inspector Justin Medina conducted an on-site inspection at:
Well Name- Wingo, C.E. 2
Company Name- KPK
API- 05-123-12774
In Weld County Colorado.
While there, I observed PR well
During this inspection the following possible compliance issues were observed:
Annual bradenhead test. Rule 419 5. C. 3/22/24
Mechanical issues. Rule 608 .e. 3/27/24
Contaminated soil. Rule 1002..(2) D. 3/17/24
A follow up on this site inspection needs to be conducted to ensure the compliance issues
have been corrected to comply with ECMC rules.
This is a summary of inspection report.

medinaj

03/12/2024

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699505622	Inspection pictures	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6465814