

# State of Colorado Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403701764

Date Received:  
03/15/2024

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:  
 2 of 2 CAs from the FIR responded to on this Form  
 2 CA Completed  
 0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 96850  
 Name of Operator: TEP ROCKY MOUNTAIN LLC  
 Address: 1058 COUNTY ROAD 215  
 City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:  
 Name: \_\_\_\_\_  
 Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
 Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>.TEP</u>		<u>COGCCInspectionReports@terraep.com</u>

### COGCC INSPECTION SUMMARY:

FIR Document Number: 708902481  
 Inspection Date: 12/12/2023 FIR Submit Date: 12/12/2023 FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850  
 Address: 1058 COUNTY ROAD 215  
 City: PARACHUTE State: CO Zip: 81635

### LOCATION - Location ID: 323991

Location Name: WPX Energy Number: RMV 108-4 County: \_\_\_\_\_  
 Qtrqr: Lot 2 Sec: 4 Twp: 7S Range: 94W Meridian: 6  
 Latitude: 39.473361 Longitude: -107.888863

### FACILITY - API Number: 05-045-00 Facility ID: 323991

Facility Name: WPX Energy Number: RMV 108-4  
 Qtrqr: Lot 2 Sec: 4 Twp: 7S Range: 94W Meridian: 6  
 Latitude: 39.473361 Longitude: -107.888863

### CORRECTIVE ACTIONS:

<b>1</b>	CA# 189156	Corrective Action: <div style="border: 1px solid black; padding: 5px;">Operators are responsible for ensuring that operations are conducted with due regard for the safety of employees, for the preservation and conservation of property, and for protecting and minimizing adverse impacts to public health, safety, welfare, the environment, and wildlife resources.</div>	Date: <u>12/15/2023</u>
	Response: <u>CA COMPLETED</u>	Date of Completion: <u>12/19/2023</u>	
	Operator Comment:	<div style="border: 1px solid black; padding: 5px;">The electrical line was installed and the trench has been backfilled. Corrective Action complete.</div>	

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**2** CA# 189157

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved.

Date: 12/19/2023

Response: CA COMPLETED

Date of Completion: 12/19/2023

Operator Comment:

The trench has been backfilled with stockpiled soils. Corrective Action complete.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**OPERATOR COMMENT AND SUBMITTAL**

Comment: CA #189156: The electrical line was installed and the trench has been backfilled. Corrective Action complete.  
CA #189157: The trench has been backfilled with stockpiled soils. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: \_\_\_\_\_

Title: TEP Representative

Date: 3/15/2024 3:08:53 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files