

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403706691

Date Received:

03/15/2024

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 708902245

Inspection Date: 11/16/2023

FIR Submit Date: 11/16/2023

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

### LOCATION - Location ID: 323890

Location Name: BARRETT-66S94W Number: 35NESW County: \_\_\_\_\_

Qtrqtr: NESW Sec: 35 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.477130 Longitude: -107.858140

### FACILITY - API Number: 05-045-

-00

Facility ID: 456905

Facility Name: Domestic Tap

Number: 35NESW

Qtrqtr: NESW Sec: 35 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.477130 Longitude: -107.858140

### CORRECTIVE ACTIONS:

1 CA# 188312

Corrective Action: All Production Facilities, valves, pipes, fittings, and vessels will be securely fastened or sealed, inspected at regular intervals, and maintained in good mechanical condition.

Date: 11/19/2023

Response: CA COMPLETED

Date of Completion: 11/27/2023

Operator  
Comment:

PRV leak was fixed and a cap was added. Corrective Action complete.

COGCC Decision: \_\_\_\_\_

|                       |  |  |                                       |
|-----------------------|--|--|---------------------------------------|
| COGCC Representative: |  |  |                                       |
| <b>2</b>              | <b>CA# 188313</b>  |  |                                       |
| Corrective Action:    | Vents on pressure safety devices will be designed to be clear and free of debris and water at all times. |  | Date: <u>11/23/2023</u>               |
| Response:             | CA COMPLETED   |  | Date of Completion: <u>11/27/2023</u> |
| Operator Comment:     | PRV leak was fixed and a cap was added. Corrective Action complete.                                      |  |                                       |
| COGCC Decision:       |  |  |                                       |
| COGCC Representative: |  |  |                                       |

|   |  |
|---|--|
| <b><u>OPERATOR COMMENT AND SUBMITTAL</u></b>  |  |
| Comment:  | CA #188312: PRV leak was fixed and a cap was added. Corrective Action complete.<br>CA #188313: PRV leak was fixed and a cap was added. Corrective Action complete. |
| I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete. |  |
| Print Name: <u>Jordan Veith</u>   | Signed: _____  |
| Title: <u>TEP Representative</u>  | Date: <u>3/15/2024 4:36:30 PM</u>  |

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|------------------------|--------------------|
|                        |                    |

Total Attach: 0 Files