

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/18/2024

Submitted Date:

03/18/2024

Document Number:

702502487

FIELD INSPECTION FORM

 Loc ID 313042 Inspector Name: Burchett, Kirby On-Site Inspection 2A Doc Num: _____
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 OGCC Operator Number: 7125
 Name of Operator: BEEMAN OIL & GAS INC
 Address: 13635 E 104TH AVENUE STE 400
 City: COMMERCE CITY State: CO Zip: 80022
Findings:

- 9 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Pate, James	(720) 377-3366	jspconcrete@yahoo.com	
Lawton, Lisa	(970) 846-4639	lisa@beemanoil.com	
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	
Galloway, Kelly	(970) 210-2896	kgalloway.werc@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223429	WELL	SI	01/01/2024	OW	081-06795	ELK SPRINGS UNIT 23B-8	SI

General Comment:[ECMC Inspection Report Summary](#)

On Monday, 03/18/2024, Inspector Kirby Burchett, conducted a routine field inspection at Beeman Oil & Gas Inc. on the Elk Springs Unit 23B-8 well, Location #313049, in Moffat County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District, High Priority area with NSO, Density and Other Consultation Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

While there during normal operations the following compliance issues were observed:

- Oily waste and stained soil.
- Open ended load line.

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

Location

Overall Good:

Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

Spills:			
Type	Area	Volume	
Lube Oil	Pump Jack	<= 1 bbl	
Comment:	Oily waste at engine. Stained soil below.		
Corrective Action:	Remove and properly dispose of oily waste and impacted soil.		Date: 04/03/2024

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	3 rail		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Lube oil tank in containment		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		

Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	HEATED STEEL AST		
Comment:	Open ended load line				
Corrective Action:	All load lines or tank valves that can be used as a load line will be capped or plugged.				Date: 03/24/2024

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:	Unlined			
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 223429 Type: WELL API Number: 081-06795 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention		
		Culverts				
		Ditches				

Comment: Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702502488	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6472092