

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403706728

Date Received:  
03/19/2024

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

#### Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 708902197

Inspection Date: 11/08/2023

FIR Submit Date: 11/11/2023

FIR Status: \_\_\_\_\_

#### Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

#### LOCATION - Location ID: 335572

Location Name: CLOUGH-66S94W Number: 15NWNE County: \_\_\_\_\_

Qtrqtr: NWNE Sec: 15 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.529981 Longitude: -107.871900

#### FACILITY - API Number: 05-045-

-00

Facility ID: 335572

Facility Name: CLOUGH-66S94W Number: 15NWNE

Qtrqtr: NWNE Sec: 15 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.529981 Longitude: -107.871900

### CORRECTIVE ACTIONS:

1 CA# 188124

Corrective Action: Operators are responsible for ensuring that operations are conducted with due regard for the safety of employees, for the preservation and conservation of property, and for protecting and minimizing adverse impacts to public health, safety, welfare, the environment, and wildlife resources.

Date: 11/18/2023

Response: CA COMPLETED

Date of Completion: 11/28/2023

Operator Comment: Unsafe PRV and rupture disc vent lines have been replumbed so the piping is pointing upwards. Additionally, rain caps have been added to the vent lines. Corrective Action complete.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Unsafe PRV and rupture disc vent lines have been replumbed so the piping is pointing upwards. Additionally, rain caps have been added to the vent lines. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: \_\_\_\_\_

Title: TEP Representative

Date: 3/19/2024 8:29:15 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
-------------------------------	---------------------------

--	--

Total Attach: 0 Files