

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/15/2024

Submitted Date:

03/18/2024

Document Number:

713600831

**FIELD INSPECTION FORM**

Loc ID 314210 Inspector Name: COSTA, RYAN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 83130  
 Name of Operator: STRACHAN EXPLORATION INC  
 Address: 992 S 4TH AVE SUITE 100-461  
 City: BRIGHTON State: CO Zip: 80601

**Findings:**

- 5 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Harms, Jason		Jason@strachanexploration.com	
BEAR STACY L		stacy@strachanexploration.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261890	WELL	SI	09/01/2021	GW	099-06872	SPARTAN 1	RI

**General Comment:**

[This is a location inspection of the SPARTAN#1 wellsite.](#)  
[See attached photos and additional details within this report.](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	There are deep ruts along the road causing vehicle to bottom out. Rutting needs to be filled in and stabilized.		
Corrective Action:	Install or repair required BMPs per Rule 1002.f.(2)C	Date:	04/18/2024

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	There is no sign posted at the wellhead.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	05/17/2024

<b>Emergency Contact Number:</b>			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____

<b>Good Housekeeping:</b>			
Type	STORAGE OF SUPL		
Comment:	There is unused equipment pipe laying on the ground that needs to be removed.		
Corrective Action:	Comply with Rule 606.	Date:	04/18/2024

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	The fence around the tank and pumpjack are not maintained to prevent livestock entry.		
Corrective Action:	Comply with the fencing requirements per the 1002a rules	Date:	03/25/2024

<b>Venting:</b>			
Yes/No			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:			Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713600832	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6472636">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6472636</a>