

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/04/2024

Submitted Date:

03/14/2024

Document Number:

709400865

FIELD INSPECTION FORMLoc ID 311680 Inspector Name: WOLD, REED On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 72085

Name of Operator: PETRO-CANADA RESOURCES (USA) INC

Address: 5455 BRIGHTON BLVD

City: COMMERCE CITY State: CO Zip: 80022

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

4 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@chevron.onmicrosoft.com	
		abbeynewby@chevron.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
200038	WELL	PA	10/31/1994	OW	001-05040	UPRR-NOONEN 1-B	RI
311680	LOCATION	CL			-	UPRR-NOONEN-63S59W 13SESW	RI

General Comment:

This is a final and stormwater inspection for well pad and access road. Corrective actions observed during inspection include weeds (russian thistle, bull thistle & Kochia) stormwater erosion on access road. Petro-Canada is a subsidiary of Noble energy, hence forth a subsidiary of Chevron through its acquisition of Noble energy.

Location				
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:				Date: _____
Corrective Action:				
Good Housekeeping:				
Type	WEEDS			
Comment:	Failure to control and manage weeds (russian thistle, bull thistle & kochia) to prevent weed waste and prevent the spread of seeds onto adjacent lands.			
Corrective Action:	Comply with Rule 606 weeds			Date: 03/22/2024
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date: _____
Flaring:				
Type				
Comment:				
Corrective Action:				Date: _____

Inspected Facilities									
Facility ID:	200038	Type:	WELL	API Number:	001-05040	Status:	PA	Insp. Status:	RI
Facility ID:	311680	Type:	LOCATION	API Number:	-	Status:	CL	Insp. Status:	RI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____ Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____ Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____ Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____ Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____ Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____ Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____ Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____ Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged Pass Pit mouse/rat holes, cellars backfilled Pass

Debris removed Pass No disturbance /Location never built _____

Access Roads Regraded Pass Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present **Fail** Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

Final reclamation areas are not progressing towards 1004 revegetation standards. Perform reclamation per Rule 1004. Reseeding of native vegetation appears to be needed to meet total perennial, non-invasive uniform plant cover of at least 80 percent of reference area levels. Use surface owner seed mixture, coordinate with surface owner to acquire required mixture. Ensure erosion controls are implemented to stabilize the reseeded soil, and continue to monitor and manage the site. Weeds should be controlled in order to not impede the perennial vegetation establishment. See good housekeeping.

Corrective Action: **Comply with rule 1004. reclamation**Date **04/01/2024**Overall Final Reclamation **Fail**Well Release on Active Location ☐Multi-Well Location ☐**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Stormwater erosion on access road to site. Coordinates with other operators in the area to address the access road issues.

Corrective Action: **Comply with rule 1002. stormwater**

Date: 03/22/2024

Pits: ☐ NO SURFACE INDICATION OF PIT**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403721855	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6469368
709400893	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6469335