



<b>NON-HAZARDOUS WASTE MANIFEST</b>		Waste Profile No. <b>EPS 0510221</b>		<b>PAWNEE WASTE</b>	
Generator's Name and Mailing Address: <b>WELLINGTON OPERATING CO. 1590 EAST CITY RD 70 WELLINGTON, CO. 80549</b>		Manifest No.: <b>Nº 191414</b>			
		Facility Phone No.: <b>(970) 889-0006</b>			
Bill To Company Name: (if other than the Generator): <del>WELLINGTON OPERATING CO. 1590 EAST COUNTY ROAD 70 WELLINGTON, CO 80549</del> <b>AP WELLINGTON OPERATING CO. 15301 DALLAS PKWY #900 ADDISON, TX 75001</b>		Designated Facility Name and Site Address: <b>Pawnee Waste 47368 County Rd 118 Grover, CO 80729</b>			
Well or Site Name and AFE#/PO?Reference#: <b>GAULT-PIATT NEU #20-3</b>		Truck/Haul Container No.: <b>N007</b>		Type: <b>Belly dump</b>	
		Waste Name/Waste Type: <b>WASTE SOIL WITH PETROLEUM PRODUCTS</b>		Total Quantity: <b>22.37</b>	
Special Handling Instructions: <b>USE PPE &amp; PROCEDURES TO PREVENT PETROLEUM EXPOSURE</b>				<input type="checkbox"/> Clean Fill <input type="checkbox"/> Washout <input type="checkbox"/> PCC <input type="checkbox"/> Cleanout <input type="checkbox"/> Silt Stone <input type="checkbox"/> After Hours	
		Generator's Certification: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste			
Printed/Typed Name: <b>RANDY EVANS</b>		Signature: 		Date: <b>2/26/24</b>	
<b>Transporter Acknowledgement of Receipt of Materials</b>					
Transporter Company Name: <b>Syleen</b>		Transporter's Phone No.: <b>970-324-9938</b>			
Printed/Typed Name: <b>Shawn Foley</b>		Signature: 		Date: <b>2/26/24</b>	
Discrepancy and Waste Load Rejection Reason: (complete and attach waste rejection form to this manifest):					
Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted above:					
Printed/Typed Name: <b>Brittany Havens</b>		Signature: <b>BH</b>		Date: <b>2/26/24</b>	
Time In: <b>2:17pm</b>		Time Out:			