

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403710196

Date Received:  
03/26/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Trujillo, Aaron		aaron.trujillo@state.co.us
.TEP		COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 708902088  
Inspection Date: 10/27/2023 FIR Submit Date: 10/31/2023 FIR Status:

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 324452

Location Name: SAVAGE Number: PA 21-9 County:  
Qtrqtr: NENW Sec: 9 Twp: 7S Range: 95W Meridian: 6  
Latitude: 39.457094 Longitude: -108.005440

FACILITY - API Number: 05-045-00 Facility ID: 324452

Facility Name: SAVAGE Number: PA 21-9  
Qtrqtr: NENW Sec: 9 Twp: 7S Range: 95W Meridian: 6  
Latitude: 39.457094 Longitude: -108.005440

CORRECTIVE ACTIONS:

1 CA# 187423

Corrective Action: All load lines will be capped or plugged Date: 11/07/2023

Response: CA COMPLETED Date of Completion: 11/03/2023

Operator Comment: Plugs has been installed to the load lines. Corrective Action complete

COGCC Decision:

COGCC  
Representative:

**2** CA# 187424

Corrective Action: Comply with 1002.e and restrict travel to the production areas and designated access roads. Conduct reclamation on interim areas impacted due to vehicle travel.

Date: 11/15/2023

Response: CA COMPLETED

Date of Completion: 11/07/2023

Operator  
Comment:

Vehicle tracks traveling off the working pad have been filled in. Corrective Action complete

COGCC Decision:

COGCC  
Representative:

**3** CA# 187425

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved.

Date: 11/15/2023

Response: CA COMPLETED

Date of Completion: 11/08/2023

Operator  
Comment:

Pad has been bladed and ruts have been removed. Corrective Action complete.

COGCC Decision:

COGCC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA#187423: Plugs has been installed to the load lines. Corrective Action complete.  
CA#187424: Tracks traveling off the working pad have been filled in. Corrective Action complete.  
CA#187425: Pad has been bladed and ruts have been removed. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: \_\_\_\_\_

Title: TEP Representative

Date: 3/26/2024 4:22:56 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files