

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403711016

Date Received:

03/26/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 708301084

Inspection Date: 10/17/2023

FIR Submit Date: 10/20/2023

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 324123

Location Name: UNOCAL-66S96W Number: 29SESE County: _____

Qtrqtr: SESE Sec: 29 Twp: 6S Range: 96W Meridian: 6

Latitude: 39.490628 Longitude: -108.123937

FACILITY - API Number: 05-045-00 Facility ID: 324123

Facility Name: UNOCAL-66S96W Number: 29SESE

Qtrqtr: SESE Sec: 29 Twp: 6S Range: 96W Meridian: 6

Latitude: 39.490628 Longitude: -108.123937

CORRECTIVE ACTIONS:

1 CA# 185659

Corrective Action: Cap or install wildlife protection equipment on vent line to comply with Rule 608.a.(13).

Date: 10/25/2023

Response: CA COMPLETED

Date of Completion: 10/26/2023

Operator
Comment:

Wildlife protection has been installed to the open-ended vent. Corrective Action complete.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 185660

Corrective Action: Remove debris to comply with Rule 606.

Date: 10/27/2023

Response: CA COMPLETED

Date of Completion: 10/26/2023

Operator Comment: Debris has been removed from location. Corrective Action complete.

COGCC Decision: _____

COGCC Representative: _____

3 CA# 185661

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to comply with Rule 1002.

Date: 11/04/2023

Response: CA COMPLETED

Date of Completion: 10/26/2023

Operator Comment: Pad surface has been bladed/graded and stabilized. Corrective Action complete.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: CA#185659: Wildlife protection has been installed to the open-ended vent. Corrective Action complete.
CA#185660: Debris has been removed from location. Corrective Action complete.
CA#185661: Pad surface has been bladed/graded and stabilized. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: _____

Title: TEP Representative

Date: 3/26/2024 4:52:19 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files